

**Well Inspection**  
**Osage DNR / Environmental Protection Agency**  
**1201 Elm Street, Suite 500**  
**Dallas, Texas 75270**

|                                  |                                                                                                 |                                                  |                                   |                         |                                        |
|----------------------------------|-------------------------------------------------------------------------------------------------|--------------------------------------------------|-----------------------------------|-------------------------|----------------------------------------|
| <b>Inspector</b>                 | Matthew Allen                                                                                   | <b>Inspection Date</b>                           | 10/02/2024                        | <b>Time</b>             | 09:15                                  |
|                                  |                                                                                                 | <b>Operator Representative</b>                   | Performance Energy Resources, LLC |                         |                                        |
| <b>Operator Info</b>             | Performance Energy Resources, LLC<br>P.O. Box 628<br>Barnsdall, OK 74002<br>Phone: 918-847-2531 | <b>Inventory ID</b>                              | OS4530000                         |                         |                                        |
|                                  |                                                                                                 | <b>API Well No</b>                               |                                   |                         |                                        |
|                                  |                                                                                                 | <b>Lease Name</b>                                | JACKSON                           |                         |                                        |
|                                  |                                                                                                 | <b>Well ID</b>                                   | 12                                |                         |                                        |
| <b>Location</b>                  | SE 03 24N 11E                                                                                   | <b>Status</b>                                    | Inactive                          | <b>Well Type</b>        | Disposal                               |
| <b>Latitude</b>                  | 36.582553                                                                                       | <b>Longitude</b>                                 | -96.107735                        |                         |                                        |
| <b>Inspection Reason</b>         | Plugging Witnessed                                                                              | <b>Responsible Company at Time of Inspection</b> | Performance Energy Resources      |                         |                                        |
| <b>Inspect No.</b>               |                                                                                                 | <b>Date Last MIT</b>                             | 01/23/2018                        | <b>Last Test Result</b> | Fail                                   |
| <b>Casing</b>                    | 4.5                                                                                             | <b>Tubing</b>                                    |                                   | <b>USDW</b>             |                                        |
| <b>Monitoring Device Elected</b> | N                                                                                               | <b>Tubings</b>                                   |                                   | <b>Annulus</b>          | <b>AUTHORIZED</b>                      |
| <b>Monitoring Device</b>         |                                                                                                 | <b>Fittings</b>                                  | N                                 | N                       | <b>Max Pressure</b> 542                |
| <b>FLM Canister Pressure</b>     |                                                                                                 | <b>Actual Pressure</b>                           |                                   |                         | <b>Max Volume</b>                      |
| <b>Lease Status</b>              |                                                                                                 | <b>Determined?</b>                               |                                   |                         | <b>Max Inj Units</b> Barrels Per Month |
| <b>Barrel Monitor Hooked Up?</b> | N                                                                                               | <b>Static Fluid Level</b>                        |                                   |                         |                                        |
| <b>Barrel Fluid Level (%)</b>    |                                                                                                 | <b>Determined?</b>                               |                                   |                         |                                        |
| <b>Flowline Hooked Up?</b>       | N                                                                                               | <b>Injection Rate (bpd)</b>                      |                                   |                         |                                        |
| <b>Injecting</b>                 | N                                                                                               |                                                  |                                   |                         |                                        |
| <b>Inspection Comments</b>       | Inspector observed surface restoration was completed at the well location.                      |                                                  |                                   |                         |                                        |
| <b>Inspector Signature</b>       |                                                                                                 |                                                  |                                   |                         |                                        |
| <b>Supervisor Signature</b>      |                                                                                                 |                                                  |                                   |                         |                                        |

## Appendix 1

### Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## Photograph Log

Photo No. 1

|                                 |                      |                 |
|---------------------------------|----------------------|-----------------|
| Location: 36.582553, -96.107735 |                      |                 |
| City: Barnsdall                 | County/Parish: Osage | State: Oklahoma |



**Photo File Name:** R0010516

**Orientation:** NNE

**Date of Photo:** 10/02/2024

**Time of Photo:** 9:18 AM

**Latitude:** 36.582553

**Longitude:** -96.107735

**Photographer:** Matthew Allen

**Description:** This was the well location for well OS4530000 after surface restoration had been completed.