

Identification markings on these parts can only be ascertained by first identifying part numbers for each brake lining part for each year and then retrieving engineering drawings for each part.

Chrysotile for drum brake linings was purchased from:

Asbestos Fibre Corp. Asbestos Corporation, Ltd. c/o C. L. Zimmerman Co. N-303 Cincinnati Union Terminal Cincinnati, Ohio 45203	1939 - 1975
Asbestos Corp., Ltd.	1967 - 1970
Johns Manville Corp. Box 517 Toledo, Ohio	1975 - 1984
Lake Asbestos of Quebec, Ltd. Box 608 Black Lake, Quebec	1977 - Present
JM Asbestos Sales, Inc. Asbestos, Quebec	1984 - Present

GM has purchased disc brake linings that others manufactured to install on its automobiles and light duty trucks. To the best knowledge of GM right now, the following suppliers and approximate dates have been identified, but from information available, it is impossible to determine if all product supplied during the times indicated were asbestos-containing because the presence or absence of asbestos in linings is not reflected in the records from which the following data was obtained.

The assembly consists of a lining and steel shoe. Markings on linings not manufactured by General Motors: