

FILE NAME: International Harvester (INTH)

DATE: 1978 Jan

DOC#: INTH019

DOCUMENT DESCRIPTION: Report - Industrial Hygiene Survey Follow up

INDUSTRIAL HYGIENE SURVEY FOLLOW-UP

SUBMIT THIS FORM AT 30-DAY INTERVALS FOLLOWING DATE OF REPORT

TO: Employee Environmental
Health & Safety
World Headquarters
1st Floor

Covering Survey

Written By: *John A. J. Baccia* 116 1978

Dates Survey

Was Conducted: *Aug 15 & 16*

EMPLOYEE ENVIRONMENTAL HEALTH & SAFETY			
RJH			
116 1978			
RFM	EL	ELA	DSJ
116	116	116	116
FILE # 116			

Indicate the survey items by number on the appropriate lines below, and add remarks if necessary.

COMPLETED - Explain only if comment is necessary for clarification.

1-3-4-6-7-9-10-11

IN PROCESS - List items which will require more time to complete, and give estimated completion dates. Explain only if necessary.

#2 *have bids being figured, repair and adjustment to pump tests have reduced noise level considerably - all operators have ear protection to wear pending more equipment. Completion by 3-1-78*
#5 *more bids being sought for duct work - one bid received was excessive high - two other Bids declined to bid. Completion by 3-1-78*

CANNOT COMPLETE - Give reason.

#8 *awaiting instructions from W. H.*

All items pertaining to the above survey have now been completed (or cannot be completed).

☐

SIGNATURE: *C. B. Rose*

LOCATION: *Atlanta Renew Center 689*

DATE: *Jan 13-1978*

INDUSTRIAL HYGIENE SURVEY FOLLOW-UP

SUBMIT THIS FORM AT 30-DAY INTERVALS FOLLOWING DATE OF REPORT

TO: Employee Environmental
Health & Safety
World Headquarters
1st Floor

Covering Survey

Written By: *John A. J. Baccia* 116 1978

Dates Survey

Was Conducted: *Aug 15 & 16*

EMPLOYEE ENVIRONMENTAL HEALTH & SAFETY			
RJH			
116 1978			
RFM	EL	ELA	DSJ
116	116	116	116
FILE # 116			

Indicate the survey items by number on the appropriate lines below, and add remarks if necessary.

COMPLETED - Explain only if comment is necessary for clarification.

1-3-4-6-7-9-10-11

IN PROCESS - List items which will require more time to complete, and give estimated completion dates. Explain only if necessary.

#2 *have bids being figured, repair and adjustment to pump tests have reduced noise level considerably - all operators have ear protection to wear pending more equipment. Completion by 3-1-78*
#5 *more bids being sought for duct work - one bid received was excessive high - two other Bids declined to bid. Completion by 3-1-78*

CANNOT COMPLETE - Give reason.

#8 *Awaiting Instructions from W. H.*

All items pertaining to the above survey have now been completed (or cannot be completed).

☐

SIGNATURE: *C. B. Rose*

LOCATION: *Atlanta Renew Center 689*

DATE: *Jan 13-1978*