

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID EPA Well ID#: 2021–11–18 EPA Permit # (or RA): Page 1 Of 2										
Inspector(s): <u>Anthony Shelton</u> (lead), <u>Carl Weller</u> <u>Carol Chen</u>					Start Time: <u>1:10 pm</u> End Time: <u>1:20 pm</u>										
Facility Contact Information	Facility Name: <u>PETRO HARVESTER OPERATING COMPANY, LLC</u>														
	Street Address: <u>1107 W 6th St (office address)</u>														
	City: <u>Laurel</u>					County: <u>Jones</u>					State: <u>MS</u> Zip: <u>39440</u>				
	Nature of Business: <u>Oil and gas extraction industry</u>														
	Facility Owner/Operator: <u>PETRO HARVESTER OPERATING COMPANY, LLC</u>										Phone: <u>601-651-2100</u>				
	Email: <u>kerry.allen@rockallenergy.com</u>														
	Facility Contact (if different): <u>Kerry Allen, Sr. Operations Manager</u>										Phone: <u>601-651-2105</u>				
	O/O Mailing Address: <u>1107 W 6th St (office address)</u>														
City: <u>Laurel</u>					County: <u>Jones</u>					State: <u>MS</u> Zip: <u>39440</u>					
Well Data from File	Well Name & #: <u>CITY OF LAUREL (COL) 31-14 #2</u>														
	Well Type (see table): <u>Enhanced Recovery, UIC Class II</u>										State Permit: <u>API#2306720437-01-00</u>				
	Latitude (°N): <u>31.69613</u>					Longitude (°W): <u>-89.14129</u>					Elevation (ft): <u>218'(Gr)</u>				
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD 12,418 ☐ Other: _____														
	Total Depth (ft): <u>13,713'</u>					Inner Casing Size (in): <u>7"</u>					Tubing Size (in): <u>2 7/8"</u> Packer Depth (ft): <u>11,748'</u>				
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) <u>11,875'</u> Bottom(ft): <u>12,400'</u> Max. Injection Pressure (psig): <u>2,600 psi</u>														
	Latitude (°N): <u>31.69632</u>					Longitude (°W): <u>-89.14141</u>					Elevation (ft): _____				
EPA GPS ID: <u>SX8123</u> Well Status (see table): <u>AC</u> If not Active, Reported Date Last Active: _____															
Nature of Injected Fluid(s) if any: <u>Produced fluids</u>															
General Condition of the Well Site: <u>NA</u>															
Field Measurements and Observations	Notes & Comments (include discrepancies from database values): <u>Tubing gauge reads: 2,160 psi Annulus gauge reads: 0 psi</u>														
	Perforations (given by field hand on-site):														
	<u>11,875' to 11,898'</u>					<u>12,279' to 12,286'</u>									
	<u>11,926' to 11,948'</u>					<u>12,385' to 12,400'</u>									
	<u>11,985' to 12,050'</u>														
	<u>12,066' to 12,143'</u>														
	<u>12,238' to 13,243'</u>														
	See reverse for additional observations, comments and photo log														
Owner/Operator Representative (Optional) Name: _____ Signature: _____										UIC Inspector Name: <u>Anthony Shelton</u> Signature: _____					

Class I and II Well Inspection Form
US Environmental Protection Agency – Region 4
Underground Injection Control Program
 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303
 Phone: (404)562-9424

Inspection ID	EPA Well ID#:														
	Year-Month-Day:	2	0	2	1	–	1	1	–	1	8				
	EPA Permit # (or RA):														
												Page	2	Of	2

Field Measurements and Observations (Cont.)

(Cont.) CITY OF LAUREL (COL) 31-14 #2

Team's observations/comments: We Inspected 8 wells that day, with a total of 9 people: 4 from Petro Harvester, 2 from MSOGB and 3 from EPA. All inspected wells were located in areas that were fenced and gated. All the pumping units and injection pumps were in good condition and operated almost silently. The well locations seemed to be kept clean and organized.

(TA status: inactive 2 years or more. IN status: inactive less than 2 years. PBTD: Plug back total depth - not total well depth)

Photo Log

Photographer: Carl Weller EPA Camera ID: SX8123

Photo ID: 113 Time: 1:10 pm Lat (°N): 31.69632 Long (°W) -89.14141

Description: well site Altitude 120

Photo ID: 114 Time: 1:20 pm Lat (°N): 31.69611 Long (°W) -89.14130

Description: overview Altitude 120

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Owner/Operator Representative (Optional)

Name: _____

Signature: _____

UIC Inspector

Name: Anthony Shelton

Signature: _____

Version 2018-04-18

Inspector Carl Weller's signature: _____ Inspector Carol Chen's signature: _____