

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	11/07/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	LBOC, LLC	
Facility Name:	Unknown	
Facility Physical Location:	33.317228, -92.510785	
(city, state, zip code)	Calion, Arkansas 71724	
Mailing address:	787 Baugh St.	
(city, state, zip code)	Norphlet, Arkansas 71759	
County/Parish:	Union County	
Facility Phone Number	870-546-3457	
Facility Contact:	Charles Long	
	longbrosoil@yahoo.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		12 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the LBOC, LLC oil and gas facility located at latitude 33.317228 and longitude -92.510785 near Calion, Arkansas on 11/07/2019 for an unannounced inspection. There were no representatives of LBOC, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

The tank battery was unidentified and near the Champagnolle Field. There was no sign to identify the facility during the inspection. The facility was a large tank battery.

Section II - OBSERVATIONS

I observed a small pit on the north end of the tank battery that had a drain valve in the secondary containment berms. I saw oil stains that indicated that there had been flow in the past over a steep bluff toward the Ouachita River.

Section III – AREAS OF CONCERN

There were leaks and fluids evident outside of the secondary containment area, including oil staining around the drain valve. The fluids were released towards a steep bluff toward the Ouachita River.

Section IV – FOLLOW UP

EPA will conduct a follow up inspection in approximately 6 months.

Section V – LIST OF APPENDICES

N/A