






Denotes approximate photo location

Entrance to site with culvert over stream and surrounding wetland



Denotes approximate photo location




Description:
Stormwater detention basin
near Flint street entrance

Inspection Date: 9/18/2024


Cranberry Meadows Estate

Photo 2

ED_019088A_00004093-00002



ED_019088A_00004093-00004



Denotes approximate photo location




Description:
Catch basin without proper
sediment protection

Inspection Date: 9/18/2024


Cranberry Meadows Estate

Photo 5


ED_019088A_00004093-00005



← Denotes approximate photo location




Description:
Dry Well infiltration device




A black and white photograph of a forest path. The path is covered in fallen leaves and leads into a dense forest. A large pile of rocks or debris is visible on the left side of the path.

ED_019088A_00004093-00007




A black and white photograph of a forest clearing. In the foreground, there is a large pile of cut logs and branches. A person is visible in the background, standing near a small structure or tent. The forest is dense with tall trees.

ED_019088A_00004093-00008




A black and white photograph of a landscape. In the foreground, a low, rustic stone wall made of irregular rocks runs across the bottom. Behind the wall, a large, light-colored pile of rocks or debris sits on a grassy slope. The background is filled with a dense forest of tall, thin trees, possibly pines or cypresses, under a bright sky. The image has a high-contrast, grainy quality.

ED_019088A_00004093-00009



A black and white photograph showing a steep, eroded bank. The top of the bank is covered in dense, dark vegetation, including many ferns. A single, light-colored tree trunk stands vertically on the left side of the upper bank. The lower portion of the bank is exposed, revealing a mix of soil, rocks, and some sparse, dry-looking vegetation. The overall scene suggests a natural, possibly disturbed, slope.

ED_019088A_00004093-00010



A black and white photograph showing a dark, irregularly shaped object, possibly a piece of clothing or debris, lying on a light-colored, rocky or gravelly ground. The object is partially obscured by shadows and appears to be a dark, possibly wet, material. The ground is composed of small, light-colored stones and pebbles. The overall scene is dimly lit, with strong shadows.

ED_019088A_00004093-00012