



Applied Environmental Services

"Consultants in Wastes Management and Environmental Control"


ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO

SUITE 320

EL PASO, TEXAS 79902

(915) 533-4108



17 November 1987

Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Number	Time-minutes	Flow-lpm	Fibers/cc
S-12, Area III, Personal	90	2	0.02
S-13, Area III, Area	90	15	0.01
S-14, Area I, Personal	200	2	0.01
S-15, Area I, Area	200	15	0.01

Sincerely,

Howard G. Applegate
Ph.D.



Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL, SPECIALISTS

PROJECT: CHEVRON

DATE: NOVEMBER 13, 1987

Chevron BB
015607

ANALYZED BY: DR. HOWARD APPELEGATE

DATE: November 17, 1987

SAMPLE NO.	S-12	S-13	S-14	S-15					
SAMPLE LOCATION	AREA III PERSONAL AIR SAMPLE REMOVAL	AREA III AREA SAMPLE REMOVAL	AREA I PERSONAL AIR SAMPLE REMOVAL	AREA I AREA SAMPLE REMOVAL					
FILTER SIZE (mm)	25	25	25	25					
START TIME	8:30am	8:32am	8:40am	8:41am					
END TIME	10:00am	10:32 am	12:00pm	12:01pm					
RATE OF FLOW (lpm)	2LPM	15LPM	2LPM	15LPM					
TOTAL TIME (hrs)	90	90	200	200					
VOLUME SAMPLED (l)	180	1350	400	3000					
RESULTS (f/cc)	0.02	0.01	0.01	0.01					