


Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	05/14/2025	
Media Program:	Water	
Regulatory Program(s)	CWA	
Company Name:	[REDACTED]	
Facility Name:	[REDACTED]	
Facility Physical Location:	[REDACTED]	
(city, state, zip code)		
Mailing address:	[REDACTED]	
(city, state, zip code)		
County/Parish:	Benton	
Facility Phone Number	[REDACTED]	
Facility Contact:	[REDACTED]	[REDACTED]
FRS Number:	N/A	
Identification/Permit Number:	[REDACTED]	
Media Identifier Number:	N/A	
NAICS:	112340	
SIC:	0254	
Personnel participating in inspection:		
Paul Juarez	EPA Region 6	Inspector
[REDACTED]		
[REDACTED]		
[REDACTED]		
[REDACTED]		
EPA Lead Inspector Signature/Date	PAUL JUAREZ  Digitally signed by PAUL JUAREZ Date: 2025.07.01 15:20:31 -05'00'	
	Paul Juarez	Date
Supervisor Signature/Date	 Digitally signed by BRYANT SMALLEY Date: 2025.07.01 15:35:14 -05'00'	
	Anthony Loston	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Paul Juarez (inspector) arrived at the [REDACTED] (facility) at 11:08 AM on May 14th, 2025, for an announced inspection. Inspector met with [REDACTED]

[REDACTED] at the Opening Conference. Inspector presented credentials to [REDACTED] and informed them that this was an EPA inspection to determine compliance with the Clean Water Act (CWA). The scope of the inspection is a full compliance evaluation.

FACILITY DESCRIPTION

The unpermitted facility is a breeder operation and has [REDACTED] barns. The facility can typically grow the birds to 38 weeks. The farm stocks [REDACTED] chickens per house for a total of 28,000 birds. The chickens are fed a corn-soy based diet. The operator will perform total barn clean out after every flock. Waste litter is transferred offsite to a 3rd party named [REDACTED] and records are kept of what is sent. Mortalities occur at a rate of 2.5-3% per month and are incinerated within 24 hours. The facility does not land apply. The facility has a Natural Resource Conservation Service (NRCS) approved Nutrient Management Plan (NMP). The facility was within the Lake Eucha/ Lake Spavinaw Watershed. The inspector exited the facility at 12:10 PM.

Section II - OBSERVATIONS

- The facility maintains good housekeeping.
- To avoid bacterial contamination, the facility refrains from using water for egg disinfection and uses UV light.
- A pond was observed northwest of the facility but contained no algae or duckweed.
- The facility used gravel in lieu of grass vegetated cover as per the recommendation of the Natural Resources Conservation Service (NRCS).
- No cracks or run-off was observed from the litter barn. The litter barn had high walls to prevent wind from spreading litter at the top of the piles.
- The mortality management area did not have any animal parts exposed.
- There were no signs of track out at any of the chicken houses.

Section III – AREAS OF CONCERN

None

Closing Conference

Inspector conducted a closing conference at [REDACTED] at 12:00 PM on May 14th, 2025. During the closing conference, the inspector fielded questions from facility personnel and provided information about the next steps in the inspection process.

Section IV – FOLLOW UP

No additional information was requested or received by EPA after exiting the facility on May 14th, 2025.

Section V – LIST OF APPENDICES

No Appendices.