

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	0	7	7	0	0	0	1
Year-Month-Day:					2	0	2	3	-	0	7	-	2	7	
EPA Permit # (or RA):					K	Y	I	1	0	6	1				
					Page 1					Of 2					
Inspector(s): <u>Carl Weller</u> (lead), _____ Start Time: <u>3:00</u>															
_____ End Time: <u>3:45</u>															
Facility Contact Information	Facility Name: <u>Sterling Materials</u>														
	Street Address: <u>199 Sierra Drive</u>														
	City: <u>Verona</u> County: <u>Gallatin</u> State: <u>KY.</u> Zip: <u>41092</u>														
	Nature of Business: <u>Limestone</u>														
	Facility Owner/Operator: <u>Sterling Ventures</u> Phone: <u>859-567-7300</u>														
	Email: <u>gkuhnhein@yahoo.com</u>														
	Facility Contact (if different): <u>R.L. Maxwell</u> Phone: <u>859-705-6082</u>														
	O/O Mailing Address: <u>100 Sierra Drive</u>														
City: <u>Verona</u> County: <u>Gallatin</u> State: <u>KY.</u> Zip: <u>41092</u>															
Well Data from File	Well Name & #: <u>Injection Well #1</u>														
	Well Type (see table): <u>Class 1</u> State Permit: <u>N/A</u>														
	Latitude (°N): <u>38.830003</u> Longitude (°W): <u>-84.759794</u> Elevation (ft): <u>665'</u>														
	Injection Method (check applicable): ☒ Casing Injector; ☐ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: <u>roof of mine</u>														
	Total Depth (ft): <u>484'</u> Inner Casing Size (in): <u>10"</u> Tubing Size (in): <u>8"</u> Packer Depth (ft): <u>no pkr</u>														
Inj. Zone: ☒ Open Hole; ☐ Perforated; Top(ft) _____ Bottom(ft): _____ Max. Injection Pressure (psig): _____															
Field Measurements and Observations	Latitude (°N): <u>83.00005</u> Longitude (°W): <u>-84.759794</u> Elevation (ft): <u>665'</u>														
	EPA GPS ID: <u>sx8123</u> Well Status (see table): <u>AC</u> If not Active, Reported Date Last Active: _____														
	Nature of Injected Fluid(s) if any: <u>None Hazardous Lime Stabilized Pickle Liquor Sludge</u>														
	General Condition of the Well Site: _____														

	Notes & Comments (include discrepancies from database values): _____														
	<u>During conversation it was stated that Leachate from Landfill may also be Injected</u>														

See reverse for additional observations, comments and photo log															
Owner/Operator Representative (Optional)								UIC Inspector							
Name: <u>R.L. Maxwell</u>								Name: <u>Carl Weller</u>							
Signature: _____								Signature: <u>CARL WELLER (Affiliate)</u> Digitally signed by CARL WELLER (Affiliate) Date: 2023.09.05 10:43:50 -04'00'							
Version 2018-04-18															

Inspection ID	EPA Well ID#:	K	Y	S	0	7	7	0	0	0	1
	Year-Month-Day:	2	0	2	3	-	0	7	-	2	7
	EPA Permit # (or RA):	K	Y	I	1	0	6	1			

Page 2

Of 2

Field Measurements and Observations (Cont.)

[illegible]

Photo Log

Photographer: Carl Weller EPA Camera ID: sx8123

Photo ID: dsc00267 Time: 3:33 Lat (°N): 38.83005 Long (°W) -84.75982

Description: Close View of Injection Well

Photo ID: dsc00268 Time: 3:34 Lat (°N): 38.82999 Long (°W) -84.75990

Description: View of Injection Well and Plant

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector

Name: Carl Weller

Signature: CARL WELLER (Affiliate) Digitally signed by CARL WELLER (Affiliate)
Date: 2023.09.05 10:43:12 -04'00'