


Field Photo Report

Submitted By: Damian Bednarz

Submitted Time: April 17, 2024 12:13 PM

Project: 86 Rockingham Road, Windham, NH




Location: 42.826205947902, -71.2523405242678

Photos:



Photo ID: 1

Project: 86 Rockingham Road, Windham, NH



Location: 42.8263026278733, -71.2523451160837

Photos:




Photo ID: 2

Field Photo Report

Submitted By: Damian Bednarz

Submitted Time: April 17, 2024 12:11 PM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8261978219433, -71.2526191482091

Photos:



Description:


Photo ID: 3

Field Photo Report

Submitted By: Damian Bednarz

Submitted Time: April 17, 2024 12:09 PM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8262964094591, -71.2514803986991

Photos:




Photo ID: 4



Photo ID: 5

Project: 86 Rockingham Road, Windham, NH



Location: 42.8263181742288, -71.2514990029802

Photos:



Photo ID: 6




Photo ID: 7

ED_019088A_00004358-00007







Description:

Photo ID: 10




Photo ID: 11

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: April 17, 2024 11:52 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8286268948218, -71.2506454484171

Photos:



Photo ID: 12



Description: Basin with small breach out to stream to west

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:51 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8286535328489, -71.2505145333567

Photos:



Description: Water buildup


Photo ID: 14

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:50 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.828641773142, -71.2502789166339

Photos:



Description: Stockpile / water


Photo ID: 15

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:48 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8290188336879, -71.2495650938534

Photos:



Description: Stockpiles being used

Photo ID: 16

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:47 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8293165635956, -71.2492222942779

Photos:



Photo ID: 17



Description: Stockpiles rocks will be going offsite

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:43 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8304942423065, -71.2479737914311

Photos:



Description: Storm drains that will be going in


Photo ID: 19

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:40 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8303529597126, -71.2467024512354

Photos:



Description: Stockpile


Photo ID: 20

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:37 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8311845505703, -71.2463396434434

Photos:



Description: Rock


Photo ID: 21

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:35 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8310363892369, -71.245890191288

Photos:



Description: Continuation of berm in back


Photo ID: 22

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:34 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8308511636424, -71.2458357412538

Photos:



Description: Berm and wetland


Photo ID: 23

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:33 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8303739653482, -71.2460026199475

Photos:



Description: Stockpile


Photo ID: 24

Field Photo Report

Submitted By: Karissa Oakes


Submitted Time: April 17, 2024 11:32 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8303717995972, -71.2460043605165

Photos:



Description: Silt buildup


Photo ID: 25

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:31 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8301212232241, -71.2460243213173

Photos:



Description: Berm/ water


Photo ID: 26

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:30 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8299118283644, -71.2460262047916

Photos:



Description: Continuation of berm


Photo ID: 27

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:29 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.829364347241, -71.246805004412

Photos:



Description: Back of property


Photo ID: 28

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:26 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8295605720788, -71.2476073879047

Photos:



Description: Stockpiles


Photo ID: 29

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:24 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8296745573555, -71.2480149467877

Photos:



Description: Stockpiles


Photo ID: 30

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:22 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8295567400189, -71.2484304137979

Photos:



Description: Pipes

Photo ID: 31

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:21 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8294414123354, -71.2487391413473

Photos:



Photo ID: 32




Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:19 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8289258163162, -71.2491218254141

Photos:



Photo ID: 34




Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:17 AM

Project: 86 Rockingham Road, Windham, NH




Location: 42.8284799038424, -71.2491321544025

Photos:



Photo ID: 36



Description: Berm continues

Photo ID: 37

ED_019088A_00004358-00037

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:17 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8284380340673, -71.2493124151243

Photos:



Description: Stockpile

Photo ID: 38

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:15 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8279444986108, -71.2495918680425

Photos:



Description: Sediment buildup along edge


Photo ID: 39

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:14 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8278200699336, -71.2496694245518

Photos:



Photo ID: 40




Description: Berm structure continues

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:13 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8278315927084, -71.2501027076338

Photos:



Description: For roads


Photo ID: 42

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: April 17, 2024 11:11 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8271381637043, -71.2502524875871

Photos:



Description: Potential stormwater conveyance that leads to basin


Photo ID: 43

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:08 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8267510582231, -71.2507233861449

Photos:



Description: Entrance/exit gate


Photo ID: 44

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:08 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8264910724492, -71.2504933513485

Photos:



Description: Behind first lot on right


Photo ID: 45

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:07 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8265518187542, -71.2506595765119

Photos:



Description: Perimeter behind first lot on the right


Photo ID: 46

Field Photo Report

Submitted By: Karissa Oakes

Submitted Time: April 17, 2024 11:06 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8266049483838, -71.2507518122152

Photos:



Photo ID: 47



Description: Front right of property




Photo ID: 49

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: April 17, 2024 10:55 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8265745322428, -71.2509057430111

Photos:



Description: Basin near entrance


Photo ID: 50

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: April 17, 2024 10:54 AM

Project: 86 Rockingham Road, Windham, NH



Location: 42.8266063941331, -71.2509062750376

Photos:



Description: Berm near entrance

Photo ID: 51

Photo ID: 52