

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	09/18/2024	Time	11:30
		Operator Representative	Performance Energy Resources, LLC		
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS4629000		
		API Well No			
		Lease Name	HUDSON		
		Well ID	3		
Location	SW 20 27N 12E	Status	Inactive	Well Type	Disposal
Latitude	36.797145	Longitude	-96.043127		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Performance Energy Resources		
Inspect No.		Date Last MIT	05/14/2004	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings	Annulus	AUTHORIZED	
Monitoring Device		Fittings	N	N	Max Pressure 399
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Speedy Well Service (SWS) run in well OS4629000 to 800 feet where a casing obstruction was encountered. SWS shut down the plugging operation until a workover rig and tubing could be moved to the well location to clear the obstruction.				
Inspector Signature					
Supervisor Signature					