

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/30/2025	Time	09:00
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS0751000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name SBU			
	Allen, TX 75013	Well ID R-W9			
	Phone: 832-300-8221				
Location	SW 10 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.656191	Longitude	-96.653177		
Inspection Reason	Plugging Witnessed	Responsible Company at		CapturePoint, LLC	
		Time of Inspection			
Inspect No.		Date Last MIT	10/26/1988	Last Test Result	Fail
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 768
FLM Canister Pressure		Actual Pressure		Max Volume	
Lease Status	Active	Determined?		Max Inj Units	Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments		Inspector observed Hurricane Services Inc run in well OS0751000 and squeeze 150 sacks of class A cement from 2500 feet to 2851 feet. This was the bottom plug in the well. Plugging operations were scheduled to resume 02/03/2025.			
Inspector Signature					
Supervisor Signature					