



Washington Plaza

Fifth Avenue at Westlake, P.O. Box 1828
Seattle, Washington 98111, (206) 624-7400

SAF-IH
TEXACO USA
BUDGET SOUND
Pg. 104
6/76
PLT

truck load rack - 1 sample
laboratory - 1 sample

June, 1976 IHS by JPL

Review 5 recommendations - status

Audiometric booth calib.

Hg contamination behind instrument panel in Elec - Inst stop

disposal of asbestos waste

low hood ventilation

Breathing air - CO
high temp alarm
bottled

WISHA -

Silica - sandblasting
paint shop

PLAINTIFF'S EXHIBIT

TEX-58