

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	7	4
Year-Month-Day:					2	0	2	4	-	0	4	-	3	0	
EPA Permit # (or RA):					F	L	I	0	0	4	4				
					Page		1		Of		2				
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 10:20 am															
End Time: 10:32 am															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating, LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
City: Jay County: Santa Rosa State: FL Zip: 32565															
Well Data from File	Well Name & #: McDavid Lands Etal #37-5														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_1314-H														
	Latitude (°N): 30.994861 Longitude (°W): -87.186219 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBDT: 18806 feet ☐ Other: surface casing														
	Total Depth (ft): 18806 Inner Casing Size (in): 7 3/4" @ 16878 7 5/8" @ 0 - 12822 3 1/2" @ 16408 Baker FB														
	Packer Depth (ft): @16045														
Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):															
Field Measurements and Observations	Latitude (°N): 30.994883 Longitude (°W): -87.186058 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): NC If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values): This well is an active producer, not converted to injection. This well is utilizing nitrogen to increase the formation pressure of the Smackover Formation.														
	Tubing gauge: 0 psi														
	Production gauge: 2200 psi														
	Surface gauge: 0 psi														
	Flow line gauge:														
	See reverse for additional observations, comments and photo log														
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.06.20 21:41:43 -04'00'								Signature:							
Version 2018-04-18															

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 7 4									
Year-Month-Day: 2 0 2 4 – 0 4 – 3 0															
EPA Permit # (or RA): F L I 0 0 4 4															
Page 2 Of 2															
Field Measurements and Observations (Cont.)	(Cont) _____														
	McDavid Lands Etal #37-5														
	Photo ID: RIMG0110 Time: 10:24 am Lat (°N): 30.994883 Long (°W): -87.186058														
annular pressure gauge															
Photo ID: RIMG0111 Time: 10:28 am Lat (°N): 30.994878 Long (°W): -87.18607															
close-up view of production well															
Photo ID: RIMG0112 Time: 10:32 am Lat (°N): 30.994402 Long (°W): -87.186158															
sign showing identification of the production well															
Photo Log	Photographer: Carol Chen EPA Camera ID: S75332														
	Photo ID: RIMG0104 Time: 10:21 am Lat (°N): 30.994938 Long (°W) -87.186103														
	Description: photo of the production well, farther back														
	Photo ID: RIMG0105 Time: 10:21 am Lat (°N): 30.994928 Long (°W) -87.186067														
	Description: surface gauge														
	Photo ID: RIMG0106 Time: 10:22 am Lat (°N): 30.994923 Long (°W) -87.186062														
	Description: adjustable pressure meter														
	Photo ID: RIMG0107 Time: 10:22 am Lat (°N): 30.994896 Long (°W) -87.18607														
	Description: tubing gauge - is difficult to read the gauge in this photo, too grayish														
	Photo ID: RIMG0108 Time: 10:23 am Lat (°N): 30.994972 Long (°W) -87.186122														
Description: lower portion of the wellhead															
Photo ID: RIMG0109 Time: 10:24 am Lat (°N): 30.994892 Long (°W) -87.18608															
Description: annular pressure gauge															
UIC Inspector					UIC Inspector										
Name: Carol Chen					Name: _____										
Signature: CAROL CHEN					Signature: _____										
Digitally signed by CAROL CHEN Date: 2024.06.20 21:42:08 -04'00'					Version 2018-04-18										