

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/12/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Contango Midstream Company	
Facility Name:	Metcalf 24-2	
Facility Physical Location:	36.015162, -96.944837 (SW Sect. 24, T 18N, R 3E)	
(city, state, zip code)	Cushing, Oklahoma 74023	
Mailing address:	10300 Greenbriar Place	
(city, state, zip code)	Oklahoma City, Oklahoma 73159	
County/Parish:	Payne County	
Facility Phone Number	713-236-7466	
Facility Contact:	Alison Denner	
FRS Number:	N/A	
Identification/Permit Number:	OKU000889	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		16 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Contango Midstream Company oil and gas facility located near Cushing, Oklahoma on 03/12/2020 for an unannounced inspection. There were no representatives of Contango Midstream Company present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Metcalf 24-2. The facility was previously identified by EPA ID No. OKU000805 and has an open Administrative Order, (Docket No. 06-2014-1790). This tank battery area was the site of a previous spill of produced water from the secondary containment pit.

Section II - OBSERVATIONS

I observed a large pit east of the tank battery that was dry. The secondary containment at the tank battery was lined as well. I saw the nearby creek to this site, which was flowing east during the inspection. With a calibrated YSI Pro 30 conductivity meter, I took a reading at the creek that was below 1,000 milligrams per liter (mg/L) Total Dissolved Solids (TDS) indicating no contamination from produced water was present during the inspection.

Section III – AREAS OF CONCERN

N/A

Section IV – FOLLOW UP

N/A

Section V – LIST OF APPENDICES

N/A