



Applied Environmental Services

"Consultants in Wastes Management and Environmental Control"

ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO

SUITE 320

EL PASO, TEXAS 79902

(915) 533-4108

PLAINTIFF'S EXHIBIT

CHV-802

03 December 1987

Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas: —

The following sample were run for asbestos using method NIOSH 7400A:

Number	Time-minutes	Flow-lpm	Fibers/cc
S-38, Area I, pers — B-pipeway	210	2	<0.01
S-39, Area I, area — B-pipeway	210	15	<0.01
S-40, area I, pers — C-pipeway	180	2	<0.01
S-41, area I, area — C-pipeway	180	15	<0.01

Sincerely,


Howard G. Applegate
Ph.D.



Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL

PROJECT: CHEVRON

DATE: NOVEMBER 30, 1987

ANALYZED BY: DR. HOWARD APPELEGATE

DATE: DECEMBER 2, 1987

SAMPLE NO.	S-32	S-33						
SAMPLE LOCATION	AREA I AREA SAMPLE PRE- REMOVAL	AREA I PERSONAL SAMPLE REMOVAL						
FILTER SIZE (mm)	25	25						
START TIME	8:45 am	8:50 am						
END TIME	4:05 pm	4:15 pm						
RATE OF FLOW (lpm)	15	2						
TOTAL TIME (hrs)	7:20	7:25						
VOLUME SAMPLED (l)	6600	880						
RESULTS (f/cc)	0.01	< 0.01						