

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/22/2025	Time	12:35
		Operator Representative	Warrior Exploration & Production, LLC		
Operator Info	Warrior Exploration & Production, LLC P.O. Box 711 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS6483000		
		API Well No			
		Lease Name	Black Dogs Band		
		Well ID	3-31		
Location	SW 31 23N 12E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.42216	Longitude	-96.06386		
Inspection Reason	Compliance	Responsible Company at Time of Inspection	Warrior Exploration		
Inspect No.		Date Last MIT	01/10/2018	Last Test Result	Acceptable
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure
FLM Canister Pressure		Actual Pressure			Max Volume 90000
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed well OS6483000 was converted to production. At the time of the inspection the well was actively producing via pumpjack.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.42216, -96.06386		
City: Skiatook	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010567

Orientation: S

Date of Photo: 1/22/2025

Time of Photo: 1:37 PM

Latitude: 36.42216

Longitude: -96.06386

Photographer: Matthew Allen

Description: This was well OS6483000 at the time of the inspection. The well was actively producing at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.42216, -96.06386		
City: Skiatook	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010568

Orientation: ESE

Date of Photo: 1/22/2025

Time of Photo: 1:37 PM

Latitude: 36.42216

Longitude: -96.06386

Photographer: Matthew Allen

Description: This was well OS6483000 with a pumpjack and rod pump installed and actively producing at the time of the inspection.