

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/15/2024	Time	10:00
		Operator Representative	Bandwheel Production Company, LLC		
Operator Info	Bandwheel Production Company, LLC P.O. Box 700426 Tulsa, OK 74170 Phone: 918-932-8418	Inventory ID	OS3272000		
		API Well No			
		Lease Name	Bandwheel		
		Well ID	CI-14		
Location	NW 13 23N 08E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.474521	Longitude	-96.398796		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Bandwheel Production Company,		
Inspect No.		Date Last MIT	03/03/2023	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 404
Lease Status		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Lester well service run tubing in hole to 1450 feet below the surface and spot 50 sacks of cement for the bottom plug. Top plug placement scheduled for following day.				
Inspector Signature					
Supervisor Signature					