



Photographs for City of Belcourt Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 456 taken by **Privacy** on 8/22/2023.

Description:

South Cluster control panel. Seal fail light was illuminated.



Photo number 457 taken by **Privacy** on 8/22/2023.

Description:

South Cluster wet well.





Photographs for City of Belcourt Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 458 taken by **Privacy** on 8/22/2023.

The direction of the photo is South.

Description:

Overview of cell 1.



Photo number 459 taken by **Privacy** on 8/22/2023.

Description:

South Belcourt lift station control panel.





Photographs for City of Belcourt Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 460 taken by **Privacy** on 8/22/2023.

Description:

South Belcourt lift station wet well.



Photo number 461 taken by **Privacy** on 8/22/2023.

The direction of the photo is West.

Description:

Overview of cell 5.





Photographs for City of Belcourt Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 462 taken by **Privacy** on 8/22/2023.

The direction of the photo is Northeast.

Description:

Overview of cells 1, 2 and 3.

