


SKID FABRICATION • DESIGN • MAINTENANCE • CIVIL • STRUCTURAL • ERECTION
PIPE FABRICATION • FIRE PROTECTION

P. O. BOX 9014 • CORPUS CHRISTI, TEXAS 78469 • (512) 289-5272



August 21, 1989

TO: Charlie Cockrill
FROM: Brack Routh
SUBJECT: Suspected Asbestos - Ultraformer Unit



DMW
CSW


File
SAM

At approximately 12:45 p.m. Erwin Krejci and the writer were making a walk through of Area 24. We noticed some Asbestos looking material laying on the ground east of DA 2400. Approximately 6" - 8" of material had been removed from a 6" line.

Mr. Krejci then informed Joe Harris, Koch representative, to identify this material, which he did as Asbestos. He in turn cleaned up the area and removed approximately 30" of this material from the 6" line.

In my discussion with James Herzog, H & S Forman, he was informed by two Koch operators on Saturday, August 19, to remove this material. He did not get to it till approximately 11:00 a.m. today. Approximately 6" - 8" of this material on one side of the 6" line was removed at this time.

Mr. Harris cleaned up the area with a permit written at 1:20 p.m. today.


Brack Routh

cw:BDR

CC: Shirley A. Miller
Dan Kincade
Michael D. Scott
Erwin Krejci
Joe Harris

K018519

MOD Date

1. Complaint Number

72409790

2. Employer Name

BAY, INC.

3. Site Location (Street, City, State, ZIP)

Koch Refining, Suntime Road, Corpus Christi, Texas

4. Mailing Address (If different) (Street, City, State, ZIP)

P.O. Box 9908, Corpus Christi, Texas 78469

5. Management Official

Bobby Day, Foreman/Tom Nolan, Supervisor

6. Telephone Number

512-289-6600

7. Type of Business

Plant Maintenance

8. Hazard Description. Describe briefly the hazard(s) which you believe exist. Include the approximate number of employees exposed to or threatened by each hazard.

(1) Employees taking out pipe were potentially exposed to asbestos. No PPE given

to employees. Demolition project in the rear of plant. Employees enter

gate #4 to get to project.

March 21

9. Hazard Location. Specify the particular building or worksite where the alleged violation exists:

(Gate 4 demolition at rear of plant.)

BAY, Inc.

K018520