

## INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

| Inspection Information                                           |                                              |
|------------------------------------------------------------------|----------------------------------------------|
| Inspection Date(s):                                              | 06/15/2023                                   |
| EPA Region/Program Conducting Inspection:                        | U.S. EPA, Region 4<br>Air Enforcement Branch |
| Company Name:                                                    | Performance Diesel Service, LLC              |
| Facility Name:                                                   | Performance Diesel Service, LLC              |
| Facility Physical Location:<br>(street address, building/unit #) | 15539 13th Street                            |
| (city, state, zip code)                                          | Gulfport, MS, 39503                          |

| Inspection Report Revision History |               |                     |
|------------------------------------|---------------|---------------------|
| Revision #                         | Revision Date | Reason for Revision |
|                                    |               |                     |
|                                    |               |                     |
|                                    |               |                     |

### Inspector and Approval

Aleeka Broner

Field Inspector Name

ALEEKA BRONER

Signature

Digitally signed by ALEEKA  
BRONER  
Date: 2023.08.10 13:58:30 -04'00'

Date

Todd Groendyke

Name of Approving  
Official

Section Chief, SAES

Title

Groendyke, Todd

Signature

Digitally signed by Groendyke,  
Todd  
Date: 2023.08.10 14:17:51 -04'00'

Date

## FACILITY INSPECTION WORKSHEET

| General Inspection Information                                         |                                                                                                                                           |                                                       |                                                                                                                                                                |
|------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Facility Name:                                                         | Performance Diesel Service, LLC                                                                                                           | Inspection Date                                       | 6/15/2023                                                                                                                                                      |
| Facility Address:                                                      | 15539 13th Street<br>Gulfport, MS, 39503                                                                                                  | Arrival/Departure Time                                | 10:08 EDT      11:10 EDT                                                                                                                                       |
|                                                                        |                                                                                                                                           | Inspection Number/ID:                                 | 3601535675-2023                                                                                                                                                |
| Primary Facility Representative & Title:                               | Cecil R. Dubuisson III, Owner                                                                                                             | Inspector(s):                                         | Aleeka Broner, Tony Spann                                                                                                                                      |
| Facility Contact Phone/Email:                                          | 228-223-5269<br>pdsgulfport@icloud.com                                                                                                    |                                                       |                                                                                                                                                                |
| Time Inspector Presented Credentials:                                  | 10:15 EDT                                                                                                                                 | Compliance Assistance Materials Provided to Facility: | Small Business Resources Information Sheet, OECA Enforcement Alert, Exhaust System Repair Guidelines                                                           |
| Permission to Enter Facility Granted? If Yes, by whom? If No, explain. | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No                                                                       |                                                       |                                                                                                                                                                |
|                                                                        | Cecil R. Dubuisson III, Owner                                                                                                             |                                                       |                                                                                                                                                                |
| Photographer Name:                                                     | N/A                                                                                                                                       | Photograph Range:                                     | N/A                                                                                                                                                            |
| Additional Personnel Present:                                          | N/A                                                                                                                                       | Areas Discussed:                                      | <input checked="" type="checkbox"/> CBI<br><input checked="" type="checkbox"/> Equipment (OBD scanner, camera)<br><input type="checkbox"/> Safety Requirements |
| Facility Summary:                                                      | Performance Diesel Service, LLC, headquartered in Gulfport, MS, is a service shop that offers repairs and maintenance for diesel engines. |                                                       |                                                                                                                                                                |

| Facility Business Activities                |                                |                                                                                                                                                                       |                                                                    |
|---------------------------------------------|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| Types of Services<br>(check all that apply) |                                | Description/Observations<br>(types and brands of parts that are manufactured or sold, types of shop services provided, etc.)                                          | Estimated Throughput<br>(e.g., sales per month, installs per week) |
| <input type="checkbox"/>                    | Manufactures aftermarket parts |                                                                                                                                                                       |                                                                    |
| <input type="checkbox"/>                    | Sells aftermarket parts        |                                                                                                                                                                       |                                                                    |
| <input checked="" type="checkbox"/>         | Service shop                   | Facility indicated that majority of services performed include the maintenance, repair, or replacement of diesel engines, transmissions, injectors and turbochargers. | 10-15 vehicles/week                                                |
| <input type="checkbox"/>                    | Fleet                          |                                                                                                                                                                       |                                                                    |
| <input type="checkbox"/>                    | Other:                         |                                                                                                                                                                       |                                                                    |

## Clean Air Act Title II: Mobile Source Inspection

| Personnel Interviewed  |                |                                           |                                         |
|------------------------|----------------|-------------------------------------------|-----------------------------------------|
| Name                   | Title/Position | Contact Info. (e.g., email, phone number) | Interviewed by (Last name of Inspector) |
| Cecil R. Dubuisson III | Owner          | 228-223-5269<br>pdsgulfport@icloud.com    | Broner                                  |
|                        |                |                                           |                                         |
|                        |                |                                           |                                         |
|                        |                |                                           |                                         |
|                        |                |                                           |                                         |
|                        |                |                                           |                                         |

| Documents Requested                           |                                                                                                                                                                                                           |                                                       |
|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| Document(s)                                   | Status                                                                                                                                                                                                    | Notes/Comments                                        |
| Service invoices from July 2022-November 2022 | <input checked="" type="checkbox"/> Document(s) Provided <input type="checkbox"/> Document(s) Denied<br><input type="checkbox"/> Will Provide After Inspection <input type="checkbox"/> Other (see notes) | Inspectors reviewed hardcopy service invoices onsite. |
|                                               | <input type="checkbox"/> Document(s) Provided <input type="checkbox"/> Document(s) Denied<br><input type="checkbox"/> Will Provide After Inspection <input type="checkbox"/> Other (see notes)            |                                                       |
|                                               | <input type="checkbox"/> Document(s) Provided <input type="checkbox"/> Document(s) Denied<br><input type="checkbox"/> Will Provide After Inspection <input type="checkbox"/> Other (see notes)            |                                                       |
|                                               | <input type="checkbox"/> Document(s) Provided <input type="checkbox"/> Document(s) Denied<br><input type="checkbox"/> Will Provide After Inspection <input type="checkbox"/> Other (see notes)            |                                                       |
|                                               | <input type="checkbox"/> Document(s) Provided <input type="checkbox"/> Document(s) Denied<br><input type="checkbox"/> Will Provide After Inspection <input type="checkbox"/> Other (see notes)            |                                                       |

| Vehicles Inspected/Observed |                   |                                      |                             |                                                                                      |
|-----------------------------|-------------------|--------------------------------------|-----------------------------|--------------------------------------------------------------------------------------|
| VIN (last 4 digits)         | EPA Engine Family | Appearance of Tampering (Yes/No/TBD) | OBD Data Obtained? (Yes/No) | Observations (e.g., Who Performed Apparent Tampering?)                               |
| N/A                         | N/A               | No                                   | No                          | Inspectors observed the exterior of five vehicles. No photos were taken of vehicles. |
|                             |                   |                                      |                             |                                                                                      |
|                             |                   |                                      |                             |                                                                                      |
|                             |                   |                                      |                             |                                                                                      |
|                             |                   |                                      |                             |                                                                                      |
|                             |                   |                                      |                             |                                                                                      |