

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/07/2022	Time	12:26
Inspection Due	2019-09-13T00:00:00Z	Operator Representative	Bandwheel Production Company, LLC		
Operator Info	Bandwheel Production Company, LLC P.O. Box 700426 Tulsa, OK 74170 Phone: 918-932-8418	Inventory ID	OS2633000		
		API Well No			
		Lease Name	Bandwheel		
		Well ID	CI-8		
Location	NE 13 23N 08E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.475905	Longitude	-96.389878		
Inspection Reason	Compliance	Responsible Company at Time of Inspection	Bandwheel Production Company		
Inspect No.		Date Last MIT	09/13/2017	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 395
FLM Canister Pressure		Actual Pressure	160	0	Max Volume
Lease Status	Active	Determined?	Company Gage	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	At the time of inspection, well OS2633000 was connected and injecting. There were no areas of concern.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2022.10.17 22:11:25 -05'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2022.10.18 13:09:19 -05'00'				

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.475740, -96.389972		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0823

Orientation: n/a

Date of Photo: 10/07/2022

Time of Photo: 12:28 PM

Latitude: 36.475740

Longitude: -96.389972

Photographer: Matthew Allen

Description: This was the well sign for well OS2633000.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.475740, -96.389972		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0824

Orientation: NW

Date of Photo: 10/07/2022

Time of Photo: 12:28 PM

Latitude: 36.475740

Longitude: -96.389972

Photographer: Matthew Allen

Description: This was well OS2633000. There were no areas of concern at the time of the inspection.