

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/07/2025	Time	10:35
		Operator Representative	Performance Energy Resources, LLC		
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS4243000		
		API Well No			
		Lease Name	Harrison		
		Well ID	9		
Location	NW 18 26N 12E	Status	Inactive	Well Type	Disposal
Latitude	36.73265	Longitude	-96.055181		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Performance Energy Resources		
Inspect No.		Date Last MIT	02/06/2013	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 415
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Inactive	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level	418		
Barrel Fluid Level (%)		Determined?	Echo Meter		
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed well OS4243000. At the time of the inspection, the well was connected but not injecting. The tubing fluid level was observed to be 418 feet below the surface.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2025.08.12 08:15:21 -05'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2025.08.12 10:45:30 -05'00'				

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.73265, -96.055181		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010695

Orientation: NNE

Date of Photo: 07/07/2025

Time of Photo: 11:00 AM

Latitude: 36.73265

Longitude: -96.055181

Photographer: Matthew Allen

Description: This was well OS4243000 at the time of the inspection. The well was connected but not injecting.