

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	12/11/2024	Time	12:30
		Operator Representative	CapturePoint, LLC		
Operator Info	CapturePoint, LLC 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS3865000		
		API Well No			
		Lease Name	NBU		
		Well ID	102 W6		
Location	SW 06 26N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.759562	Longitude	-96.703548		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	06/09/2021	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure Lease Status		Fittings	N	N	Max Pressure 764
		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Hurricane Services Inc run in well OS3865000 to 2881 feet below the surface, load the hole with mud and spot 75 sacks of cement with 2% calcium for the bottom plug in accordance with the EPA approved plugging plan.				
Inspector Signature					
Supervisor Signature					