

UNLOADING SLIP

Car No. CONX 9074
On Spot No. _____
Material VC
From Shell Houston
Received 218,800
ANALYSIS

930
OK TO UNLOAD _____
UNLOADED INTO TK 202

Weights	Tank Reading
_____	<u>6890</u>
_____	<u>6590</u>

Date 10-29-72 By F.B.

TUCKER 42

DTH 00000394