

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/16/2024	Time	15:30
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS6067000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name NBU			
	Allen, TX 75013	Well ID 49-W32			
	Phone: 832-300-8221				
Location	SE 23 27N 05E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.798709	Longitude	-96.726489		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	10/22/2020	Last Test Result	Acceptable
Casing	5.5	Tubing	2.875	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 600
FLM Canister Pressure		Actual Pressure	400	40	Max Volume 180000
Lease Status	Active	Determined?	Company Gage	Company	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	At the time of the inspection, well OS6067000 was connected and injecting. The tubing pressure was observed at 400 psig and the annulus pressure was observed to be 40 psig. At the time of the inspection, there were no areas of concern.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2024.05.01 16:04:57 -05'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2024.05.02 07:56:34 -05'00'				

Appendix 1

Photograph Log 1 Photo

Description: This was well OS6067000 at the time of the inspection.