

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
3-31-02	6060	GC 5				179598	Charged out #10 SPOT VAPOR LINE	4/1/02	AR	DA
0100	KC	4	10	WR Nothing found Dumping 700 RX to high mole Sweco. Reading G.B. cleared next check	0	NO	Clay Brownlee			
4-1-02	6061	GC #2	7.5, 6.0							
2040	BA	7, 2								
4-1-02	6062	GC #2	7.7	Nothing found	0	NO	Nothing found at this time Clay Brownlee			
2121	BA	2								
4-1-02	6063	GC 5	10.0	#44 spot AK 07/190/336 did not unload	10	NO	Parked lines down & unhooked car Torbel	4-2	TC	
0630	DW	2, 3, 4								
4-2-02	6064			SOUTH STATION NEW EAST UN- LOADING	NO	NO	FOUND NO THING LEAK WENT AWAY AXT CHIC			
21156	AS	#1	5.3				Nothing found Chic			
4-2-02	6065			HMA DUMP PUMP AND STRAINED	0	NO	Nothing found	NA	NA	NA
23109	AS	7	10.0							

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
3-29-02	6054	GC#3		TOP OR R1740	100	yes 179559				
13:34	AS	2	6.6	EVACUATION VALVE PACKING LEAKING 82 HV 233 3.0000						
3-30-02	6055	#1	7.0/7.0	South & South Middle STATIONS	10+	NO	Tighten Nipples on spots #2 and #3 Unloading	3-30-02	EM	EM
16:00	Ch	#s 4,5	7.7/7.0							
3-30-02	6056	GC#5		SOUTH STATION NEW EAST UN- LOADING	+	NO	SNAPPY JOE DAPHNIA Busted Chin Eng. Isolated			
17:12	AS	1	10	C.E.						
3-30-02	6057	GC#5	8.3	Nothing Found						
18:54	GS			Trailing Material						
3-30-02	6058	GC#1	6.3				Tight up Snapper Joe on No 5 Spot	3-30-02	EM	EM
0346	BN	3				NO				
3-30-02	6059	#5	7.8	Not Found	NA	NA	NA	NA	NA	NA
145	Ch	#5		Cleaned Next Check						

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.