




Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

This report includes only factual information gained by documentation, onsite observations, and/or onsite interviews.

Inspector Name(s)	Stephanie Andreescu Seika Robinson (in-training) Austin Jepsky (in-training)	Time In	10:32 AM	Start Date	October 20, 2022
		Time Out	10:50 AM	End Date	October 20, 2022
Inspector's Organization	U.S. EPA Region 2				
Organization Requesting Inspection (if different)					
Inspection Type	CWA Section 404 Inspection	Inspection Status	Original		
Site Name	Thomas Endrizzi Property				
Site Address*	430 Stony Ford Road (Tax ID 61-1-5.225)				
City*	Wallkill, Middletown	County*	Orange	State*	NY
				Zip Code*	10941
Latitude/Longitude*	41.4587, -74.3154	Estimated Size of Site (acres)	44.40		
Is there a home on the site? ☒ Yes ☐ No					
Inspector Signature	 Digitally signed by STEPHANIE ANDREESCU Date: 2022.12.08 14:36:24 -05'00'			Date	12/8/22
Supervisor Signature	 Digitally signed by Finocchiaro, Marco Date: 2022.12.09 09:43:32 -05'00'			Date	12/8/12

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	Thomas Endrizzi Property	Start Date	October 20, 2022
		End Date	October 20, 2022
Inspection Purpose	Initial site visit		
Opening Conference			
☒ Presentation of Inspector Credentials			
Name and Title (Use N/A if owner/operator not available to join the inspection)			
Credentials were presented to Mr. Thomas Endrizzi (property owner)			
☒ Opening Conference			
Name of person authorizing access if applicable			
I spoke with Mr. Endrizzi over the phone to arrange the inspection.			
Notes from Opening Conference			
We explained the reason for the inspection and the pointed out the area that we were interested in inspecting.			
☐ Access Issues if Any			
Describe			
Inspection Observations and Sample Collection			
Site Owner* (Name, title and contact information)			
Mr. Thomas Endrizzi, U.S. FOIA (b)(6)			
Additional Persons Present at Inspection			
N/A			
General Site Characteristics (layout of property, etc.)			
The Site is comprised of a 44.40-acre parcel with frontage and access along Stony Ford Road on the south side of the property. Two mapped unnamed tributaries to the Wallkill River flow through the Site. The majority of the Site is forested and undeveloped. Potential wetland areas were observed on the property. A single family home and attendant structures are located along Stony Ford Road.			
Site Overview (Past inspections, site description, permits, etc.)			
EPA's Wetland Protection Section had not visited the site prior to this inspection.			
Scope of Inspection (Areas inspected or not inspected)			
EPA's inspection was limited to the southwestern portion of the parcel where piles of dirt and rock had been placed at the edge of a lawn near a wooded area.			
Environmental Conditions (e.g., wind, rain, smoke, dust, temperature, snow)			
Sunny, high 40's			

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	Thomas Endrizzi Property	Start Date	October 20, 2022
		End Date	October 20, 2022
Field Work Conducted			
Data recorded during the inspection included photographs and handwritten notes. EPA met with Mr. Endrizzi and then proceeded to the southwestern portion of the Site where piles of fill material consisting of dirt and rock had been placed into piles at the edge of a lawn. EPA walked around the fill piles. Vegetation near the piles included red oak trees (<i>Quercus rubra</i>) and other upland vegetation. Wetland indicators were not observed adjacent to the fill piles. Potential wetland areas were located further west.			
Closing Conference			
Documents Received and/or Requested During the Inspection			
N/A			
Compliance Assistance Provided (If any)			
N/A			
Observations Relayed to Site Owner/Operator			
N/A			
Actions Taken by Owner/Operator During the Inspection (If any)			
N/A			
Potential Issues of Concern Including Regulatory Citations			
N/A			
Attachments*			
☐ Maps and Sketches ☒ Photographs (including location) and Photo Log ☐ Other			
Additional Notes			

CWA 404 Inspection Photolog
Thomas Endrizzi Property
430 Stony Ford Road, Wallkill
Orange County, NY


October 20, 2022



Date: 10/20/2022
Time: 10:37 AM
Photographer: S. Robinson
Photo ID: 1 – PA200498

Description:

Piles of fill material on property



Date: 10/20/2022
Time: 10:38 AM
Photographer: S. Robinson
Photo ID: 2 – PA200499

Description:

Wooded area behind fill piles;
potential wetland in the
background



Date: 10/20/2022
Time: 10:38 AM
Photographer: S. Robinson
Photo ID: 3 – PA200500

Description:

Fill piles near wooded area



Date: 10/20/2022
Time: 10:39 AM
Photographer: S. Robinson
Photo ID: 4 – PA200501

Description:
Fill piles on property




Date: 10/20/2022
Time: 10:40 AM
Photographer: S. Robinson
Photo ID: 5 – PA200502
Description:
Fallen tree



Date: 10/20/2022
Time: 10:40 AM
Photographer: S. Robinson
Photo ID: 6 – PA200503


Description:
Wooded area on property



Date: 10/20/2022
Time: 10:42 AM
Photographer: S. Robinson
Photo ID: 7 – PA200504

Description:

Fill piles next to wooded area on property



Date: 10/20/2022
Time: 10:47 AM
Photographer: S. Robinson
Photo ID: 8 – PA200505

Description:

Fill piles on property located
between lawn and wooded area