

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Michael Blaha	Inspection Date	04/17/2024	Time	09:55	
		Operator Representative Short Oil Company				
Operator Info	Short Oil Company	Inventory ID OS1138000				
	2536 East 51st Street	API Well No				
	Tulsa, OK 74105	Lease Name ATLANTIC				
	Phone: 918-747-8200	Well ID 13				
Location	SW 19 25N 08E	Status	Inactive	Well Type	Enhanced Recovery	
Latitude	36.626934	Longitude	-96.492239			
Inspection Reason	Routine	Responsible Company at Time of Inspection		Short Oil Company		
Inspect No.		Date Last MIT	11/10/1986	Last Test Result	Fail	
Casing	5.5	Tubing	2.375	USDW		
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N Inactive N N N N	Tubings	Annulus	AUTHORIZED		
		Fittings	Y	Y	Max Pressure	638
		Actual Pressure		Max Volume		
		Determined?		Max Inj Units	Barrels Per Month	
		Static Fluid Level				
		Determined?				
		Injection Rate (bpd)				
Inspection Comments		The well was not accessible during the time of the inspection on 4/17/2024. Areas of concern during the inspection include the valves rusted shut, the threading rusted out, and quarterly fluid reports still being sent in. Two photographs were taken during the inspection and can be seen in the Inspection Photo Log.				
Inspector Signature	MICHAEL BLAHA Digitally signed by MICHAEL BLAHA Date: 2024.05.16 23:08:52 -05'00'					
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2024.05.20 11:49:26 -05'00'					

Appendix 1

Photograph Log

2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.627055, -96.492028		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010362

Orientation: N

Date of Photo: 4/17/2024

Time of Photo: 9:58 AM

Latitude: 36.627055

Longitude: -96.492028

Photographer: Michael Blaha

Description: This photo was taken looking N showing the well sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.627055, -96.492028		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010363

Orientation: N

Date of Photo: 4/17/2024

Time of Photo: 9:58 AM

Latitude: 36.627048

Longitude: -96.492038

Photographer: Michael Blaha

Description: This photo was taken looking N showing the well and inaccessible valves.