

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/29/2024	Time	10:30
		Operator Representative	Bandwheel Production Company, LLC		
Operator Info	Bandwheel Production Company, LLC P.O. Box 700426 Tulsa, OK 74170 Phone: 918-932-8418	Inventory ID	OS3259000		
		API Well No			
		Lease Name	Bandwheel		
		Well ID	CI-3		
Location	NE 13 23N 08E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.477493	Longitude	-96.391825		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Bandwheel Production Company		
Inspect No.		Date Last MIT	10/25/2011	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 397
Lease Status		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Lester Well Service run in well OS3259000 to 360 feet below the surface and circulate 35 sacks of class A cement to the surface as required by the EPA approved plugging plan. Inspector observed cement standing at the surface with no fallback. EPA inspector previously observed the bottom and middle cement plug placement in the well.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.477493, -96.391825		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010526

Orientation: WNW

Date of Photo: 10/29/2024

Time of Photo: 11:09AM

Latitude: 36.477493

Longitude: -96.391825

Photographer: Matthew Allen

Description: This was well OS3259000 at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.477493, -96.391825		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010525

Orientation: N/A

Date of Photo: 10/29/2024

Time of Photo: 11:09AM

Latitude: 36.477493

Longitude: -96.391825

Photographer: Matthew Allen

Description: This was well OS3259000 at the time of the inspection, standing full of cement to approximately 1 foot below the surface.