

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 5 7									
						Year-Month-Day: 2 0 2 4 - 0 4 - 3 0									
						EPA Permit # (or RA): F L I 0 0 1 0									
						Page 1 Of 2									
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 2:00 pm															
End Time: 2:09 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Well Name & #: St. Regis SWDS #1-3 API No. 09-113-20206 PA No. 311643														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_1093														
	Latitude (°N): 30.96806 Longitude (°W): -87.18225 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 6655' ☐ Other: surface casing 10 3/4" at 2314'														
	Total Depth (ft): 6783' Inner Casing Size (in): 7 5/8" at 6783' Tubing Size (in): Packer Depth (ft): 6106'														
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 6274' Bottom(ft): 6662' Max. Injection Pressure (psig): 1800 psi														
Field Measurements and Observations	Latitude (°N): 30.96792 Longitude (°W): -87.182311 Elevation (ft):														
	EPA GPS ID: S75322 Well Status (see table): AC If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any: Produced Waters (PW)														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	DANGER sign posted: H2S May Be Present..Authorized Personnel Only..Hazardous Operations..														
	This well is actively injecting produced waters. Tubing gauge: 800 psi														
	Production gauge: 0 psi														
	Perforations (Tuscaloosa Formation): Surface gauge: 0 psi														
	6274' to 6504' Flow line gauge: (unable to read the gauge)														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.07.09 10:49:37 -04'00'								Signature:							
Version 2018-04-18															

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	5	7
	Year-Month-Day:	2	0	2	4	-	0	4	-	3	0
	EPA Permit # (or RA):	F	L	I	0	0	1	0			
		Page					2	Of	2		

[illegible]

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID: RIMG0135 Time: 2:06 pm Lat (°N): 30.96792 Long (°W): -87.182311

Description: photo of the injection tubing does not show all of the gauge

Photo ID: RIMG0135 Time: 2:07 pm Lat (°N): 30.96895 Long (°W): -87.182325

Description: photo of the surface gauge and production gauge, both showing 0 psi

Photo ID: RIMG0135 Time: 2:08 pm Lat (°N): 30.96857 Long (°W): -87.182201

Description: produced waters manifold, near the injection well

Photo ID: RIMG0135 Time: 2:08 pm Lat (°N): 30.9678 Long (°W): -87.182178

Description: flowline gauge does not display the pressure reading, no needle and the gauge is filled with fluids

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____