

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date:	01/13/2026	
Media Program:	Water (CWA)	
Regulatory Program:	Water (CWA) Brine Program (Oil & Gas Inspection)	
Company Name:	Enerco Operating Corporation	
Facility Name:	Clark Tank Battery	
Facility Physical Location:	Off County Road 249 at 33.320769, -93.813836	
(city, state, zip code)	Genoa, AR 71840	
Mailing address:	11535 East Ricks Circle	
(city, state, zip code)	Dallas, TX 75230	
County/Parish:	Miller County	
Facility Phone Number:	870-953-0287	
Facility Contact:	Terry Collum	Field Supervisor
	terrycollum@enercooperating.com	
FRS Number:	N/A	
Identification/Permit Number:	ARU002311	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Tom McKay	EPA / Region 6	Inspector
Uma Lad	EPA / Region 6	Inspector / Enforcement Officer
Kerri McCabe	EPA / Region 6	Inspector / Enforcement Officer
Terry Collum	Enerco Operating Corporation	Field Supervisor
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Tom McKay, Uma Lad, and Kerri McCabe arrived at the Enerco Operating Corporation / Clark Tank Battery, located off County Road 415 at 33.254492, -93.953885, at 9:25 AM on 01/13/2026 for an announced inspection. We met with Terry Collum, Field Supervisor for Enerco Operating Corporation. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection. EPA previously inspected this facility on 04/15/2025.

FACILITY DESCRIPTION

EPA conducted an inspection on the Enerco Operating Corporation / Clark Tank Battery, which consists of one (1) production well.

Section II – OBSERVATIONS

I observed the facility, associated signage, and production well, see Appendix 1 (Photograph Log), Photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

Enerco Operating Corporation removed three (3) storage tanks, one (1) separator, and associated piping and loose oil (observed during the 04/15/2025 EPA inspection) and restored the surface. At the time of the inspection, no equipment remains at the facility except for the production well.

Section III – AREAS OF CONCERN

There were no areas of concern at the time of the inspection.

Section IV – FOLLOW UP

Inspector will provide the completed inspection report to the company representatives.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 2 photos taken 01/13/2026.

Appendix 1

Photograph Log

2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Facility/Location:		Enerco Operating Corporation Clark Tank Battery							
City:	Genoa		County:			State:	AR	Direction:	SW
Filename:	R0011234.JPG		Photo Date:		01/13/2026		Time:	09:25:43	
Photographer:	Uma Lad				Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing southwest and shows the sign on the production well.		
Latitude:	33°19'13.416" N	Longitude:	93°48'46.806" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Facility/Location:		Enerco Operating Corporation Clark Tank Battery						
City:	Genoa	County:	Miller	State:	AR	Direction:	SW	
Filename:	R0011235.JPG	Photo Date:		01/13/2026		Time:	09:27:38	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing southwest and shows that Enerco Operating Corporation removed the three storage tanks, separator, associated piping, and loose oil at the facility observed during the 04/15/2025 inspection and restored the surface.		
Latitude:	33°19'14.88" N	Longitude:	93°48'49.32" W