UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 8
RESOURCE CONSERVATION AND RECOVERY ACT

BASIC INFORMATION

Facility Name: H2O Management Solutions

Facility Location: 41.800700, -107.536600

RCRA ID: WYR000210419

Facility Contact: James Anbouba, 972-861-1202, janbouba@h2omsllc.com

Notification Status: Non-notifier

Date of Inspection: May 15, 2023

Arrival Time: 11:24 a.m.
Departure Time: 11:47 a.m.

Lead Inspector: Annette Maxwell, U.S. EPA

Other Attendees:

1. Dennis Lamb, Wyoming Department of Environmental Quality (WDEQ)
2. Christy Hutchinson, WDEQ
3. Dameon Baker, H2O Management Solutions

Type and Purpose of Inspection: Compliance Evaluation Inspection

Facility Type: Commercial Oilfield Waste Disposal Facility

Applicable Statute to Inspection: RCRA Section 7003

Inspection Type: Unannounced Inspection
Joint: U.S. EPA, Wyoming DEQ

FACILITY INFORMATION

Company Ownership: H2O Management Solutions, LLC

General Facility and Process Description: The H2O Management Solutions facility is a commercial oilfield waste disposal facility (COWDF) that receives non-hazardous, RCRA Subtitle C-exempt E&P oilfield waste for storage, handling and disposal. The facility has been issued a permit to operate a COWDF by WDEQ. The facility includes three evaporation ponds, a netted offload vault, storage tanks and a raw water pond.

TOUR INFORMATION

Upon arrival at the facility, an opening conference was conducted with Mr. Baker, followed by a walk-through of the facility.

Facility Name: H2O Management Solutions
Facility Location: 41.800700, -107.536600
Date of Inspection: May 15, 2023

Areas of the facility toured:

- Offload area
- Offload vault
- Evaporation ponds
- Tank storage

Data Collected and Observations: During the inspection, I observed that the netting over the offload vault was pulled back (see Attachment 1 – Photo Log). Mr. Baker stated that it was temporarily pulled back to accommodate repairs to the vault gate. On pond 1 (southernmost pond) and pond 3 (northernmost pond), I observed an emulsion on approximately 10% of the surface of the ponds. This material did not appear to present a threat to birds or other wildlife. No spills were observed in the tank battery area. No bird or other wildlife mortalities were observed in any areas of the facility that were inspected.

CLOSING CONFERENCE

A closing conference was conducted with Mr. Baker in which he stated that he would get the netting back into place over the vault.

SIGNATURE

Lead Inspector: ANNETTE MAXWELL Digitally signed by ANNETTE MAXWELL Date: 2023.07.12 05:30:51 -06'00'

Annette Maxwell, RCRA Inspector

Supervisor: JANICE PEARSON Digitally signed by JANICE PEARSON Date: 2023.07.12 15:12:36 -06'00'

Janice A. Pearson, Manager
RCRA & OPA Enforcement Branch
Enforcement and Compliance Assurance Division

Facility Name: H2O Management Solutions
Facility Location: 41.800700, -107.536600
Date of Inspection: May 15, 2023

ATTACHMENT 1 – PHOTO LOG

Photographer: Annette Maxwell
Camera Model and ID: Nikon Coolpix, B00228

Photo 1996: DSCN1996.jpg – photo of the offload vault with netting present but pulled back to accommodate repairs to the fencing.