

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 11/20/2024		Time 12:00	
Operator Representative Performance Energy Resources, LLC		Report Sent Operator			
Inject Interval Multiple		USDW 342		Well Type Disposal	
Annulus Fluid Type oil		Concentric Pkr		Packer Depth 1975	
Casing 7		Tubing 2.375			
Operator Info Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS6050000		
			API Well No		
			Lease Name OSU		
			Well ID 1A		
			Location NW 25 25N 09E		
Type of MIT Casing - Tubing Annulus Pressure			Test Reason Routine		
Injecting N		Injection Rate (bpd)		Tubular Lining	
MIT Due 11/15/2024		MIT Freq EVERY THREE YEARS		Ann Filled (hrs)	
				Ann Press Mont	
Time		Tubing Pressure		Annulus Pressure	
Pre-Test		0		0	
Initial	12:00	0	220	Flowback High	220
Mid	12:15	0	220	Mid	100 4500
Final	12:30	0	220	Low	20 3500
				End	0 1500
				Total Volume 9500	
			ADA Pressure Test - Required Test Pressure		
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)		
			Tubing Annulus		
			Depth to Top Perf/Open Hole		
			Depth to Fluid Level		
			Fluid Column Level		
			Specific Gravity of Fluid		
Nitrogen Weight Factor					
Required Pressure Test					
Remedial Action Type					
Fluid Migration Test Type				Remedial Action Type	
Inspection Comments		MIT observed, pressure hold OK. Inspector observed oil and water in the flowback.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.618449, -96.288803		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010536

Orientation: NNW

Date of Photo: 11/20/2024

Time of Photo: 1:17PM

Latitude: 36.618449

Longitude: -96.288803

Photographer: Matthew Allen

Description: This was well OS6050000 at the time of the inspection.