

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 11/20/2024		Time 12:45	
Operator Representative Performance Energy Resources, LLC		Report Sent Operator			
Inject Interval 2498 - 2511		USDW 300		Well Type Disposal	
Annulus Fluid Type water		Concentric Pkr		Packer Depth 2448	
Casing 4.5		Tubing 2.875			
Operator Info Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS6154000		
			API Well No		
			Lease Name OSU PERSHING		
			Well ID 07-11W		
			Location NE 25 25N 09E		
Type of MIT Casing - Tubing Annulus Pressure			Test Reason Routine		
Injecting N		Injection Rate (bpd)		Tubular Lining	
MIT Due 11/15/2024		MIT Freq EVERY THREE YEARS		Ann Filled (hrs)	
				Ann Press Mont	
Time		Tubing Pressure		Annulus Pressure	
Pre-Test		0		0	
Initial	12:45	0	220		
Mid	13:00	0	230		
Final	13:15	0	240		
				Flowback	Pressure
				High	240
				Mid	100
				Low	20
				End	0
				Total Volume	3100
			ADA Pressure Test - Required Test Pressure		
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)		
Fluid Migration Test Type		Remedial Action Type			
Inspection Comments		MIT observed, pressure hold OK.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.618798, -96.285823		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010537

Orientation: N

Date of Photo: 11/20/2024

Time of Photo: 2:01PM

Latitude: 36.618798

Longitude: -96.285823

Photographer: Matthew Allen

Description: This was well OS6154000 at the time of the inspection.