

VINYL CHLORIDE AND POLYVINYL CHLORIDE MANUFACTURING
COMPLEXES MONITORED BY EPA REGIONAL OFFICES
DURING MAY 1974

Louisville, Ky.	PVC Plant	The B. F. Goodrich Company B. F. Goodrich Chemical Company
Leominster, Mass.	PVC Plant	Borden, Inc. Borden Chemical Division
Plaquemine, La.	PVC Plant VC Plant	The Goodyear Tire & Rubber Company Chemical Division Dow Chemical Company
Long Beach, Calif.	PVC Plant	The B. F. Goodrich Company B. F. Goodrich Chemical Company
	PVC Plant VC Plant	American Chemical Corporation American Chemical Corporation
Painesville, Ohio	PVC Plant PVC Plant	Uniroyal, Inc. Uniroyal Chemical Division Robintech, Inc.
Delaware, City Delaware	PVC Plant PVC Plant	Stauffer Chemical Company Plastics Division Diamond Shamrock Corporation Diamond Shamrock Chemical Co.
Flemington, N.J.	PVC Plant	Tenneco, Inc. Tenneco Chemicals, Inc.

NOTES:

Water effluent samples were also collected at the PVC plant of Union Carbide Corporation, Chemical and Plastics Division, in S. Charleston, W. Va.

Sampling was attempted but was infeasible due to limited time and equipment difficulties at the PVC plants of the Firestone Tire and Rubber Company, Firestone Plastics Company, in Perryville, Md. and Pottstown, Pa.

Very limited air sampling was conducted in the Houston area in the vicinity of the plants listed below. However, in view of the inadequacy of this activity, the sampling effort in this area is being continued.

Deer Park, Tex., PVC Plant - Diamond Shamrock Corp., Diamond Shamrock Chemical Co.
Deer Park, Tex., VC Plant - Shell Chemical Co., Industrial Chemicals Div.
Houston, Texas, VC Plant - Tenneco, Inc., Tenneco Chemicals, Inc.
Pasadena, Texas, VC Plant - Ethyl Corporation