

UNION CARBIDE CORPORATION
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78520
(512) 831-4501

BULK SAMPLES:

SAMPLE NO.		DESCRIPTION
267	<i>Negative</i>	BLDG. 166 ROOF TAR S END CENTER
268	<i>Negative</i>	BLDG. 166 ROOF FIBER S END CENTER
269	<i>Negative</i>	BLDG. 167 ROOF LAYER UNDER TAR
270	<i>Negative</i>	BLDG. 167 ROOF TAR N END CENTER
300	<i>Positive</i>	BLDG. 168 PIPE
301	<i>Positive</i>	BLDG. 168 PIPE
302	<i>Negative</i>	BLDG. 161 CEILING
303	<i>Positive</i>	BLDG. 161 PIPING
304	<i>Positive</i>	BLDG. 161 FLOOR
305	<i>Positive</i>	BLDG. 162 PIPE
306	<i>Positive</i>	BLDG. 164 PIPE
307	<i>Negative</i>	BLDG. 167 CEILING
308	<i>Negative</i>	BLDG. 166 CEILING
309	<i>Negative</i>	BLDG. 221 CEILING
310	<i>Negative</i>	BLDG. 123 CEILING
311	<i>Negative</i>	BLDG. 123 FLOOR
312	<i>Positive</i>	BLDG. 123 PIPE
313	<i>Negative</i>	BLDG. 230 CEILING
314	<i>Negative</i>	BLDG. 224 CEILING
315	<i>Negative</i>	BLDG. 224 A/C DUCT
316	<i>Negative</i>	BLDG. 230 FLOOR

SAMPLE NO.	DESCRIPTION
317 <i>Positive</i>	BLDG. 420 FLOOR
318 <i>Negative</i>	BLDG. 420 CEILING
319 <i>Negative</i>	BLDG. 422 CEILING
320 <i>Negative</i>	BLDG. 424 PIPE
321 <i>Negative</i>	BLDG. 425 FLOOR
322 <i>Negative</i>	BLDG. 424 CEILING
323 <i>Positive</i>	BLDG. 424A PIPE
324 <i>Positive</i>	BLDG. 425 PIPE
325 <i>Positive</i>	BLDG. 425 A/C DUCT
326 <i>Negative</i>	BLDG. 428 FLOOR
327 <i>Negative</i>	BLDG. 428 CEILING
328 <i>Negative</i>	BLDG. 428 CEILING
329 <i>Negative</i>	BLDG. 525 CEILING
330 <i>Negative</i>	BLDG. 525 PIPE
331 <i>Negative</i>	BLDG. 523 FLOOR
332 <i>Negative</i>	BLDG. 523 CEILING
333 <i>Negative</i>	BLDG. 522 FLOOR
334 <i>Negative</i>	BLDG. 522 CEILING
335 <i>Negative</i>	BLDG. 821 FLOOR
336 <i>Negative</i>	BLDG. 821 CEILING
337 <i>Negative</i>	BLDG. 489 FLOOR
338 <i>Negative</i>	BLDG. 489 CEILING
339 <i>Negative</i>	BLDG. 625 FLOOR
340 <i>Negative</i>	BLDG. 625 CEILING

BULK SAMPLES - UNION CARBIDE BROWNSVILLE, TEXAS PAGE 3

SAMPLE NO.	DESCRIPTION
• 341 <i>Negative</i>	BLDG. 625 A/C DUCT
• 341A <i>Negative</i>	BLDG. 731 FLOOR
• 342 <i>Negative</i>	BLDG. 731 CEILING
• 343 <i>Negative</i>	BLDG. 731 A/C DUCT
• 344 <i>Negative</i>	BLDG. 731 PIPE
• 345 <i>Negative</i>	BLDG. 168 ROOF CENTER
• 346 <i>Negative</i>	BLDG. 168 ROOF B TAR
• 347 <i>Negative</i>	BLDG. 168 ROOF TOP LAYER
• 348 <i>Negative</i>	BLDG. 259 CEILING HALL
• 349 <i>Positive</i>	BLDG. 259 R. ROOM PIPE
• 371 <i>Positive</i>	BLDG. 731 ROOF (TOP)
• 372 <i>Positive</i>	BLDG. 422 PIPE IN CEILING
• 373 <i>Negative</i>	BLDG. 422 PIPE IN CEILING
• 374 <i>Negative</i>	BLDG. 731 ROOF (BOTTOM)
• 375 <i>Negative</i>	BLDG. 731 ROOF MIDDLE LAYER



UNION CARBIDE CORPORATION
COATINGS MATERIALS DIVISION

STAR ROUTE BOX 90 BROWNSVILLE, TEXAS 78521

November 7, 1990

NUS Laboratories
900 Gemini
Houston, Texas 77058

Re: Additional Samples Taken from the Union Carbide Brownsville,
Texas Plant to be Analyzed for Asbestos Fibers.

Enclosed are 60 bags containing additional samples taken from various parts of the Union Carbide Brownsville, Texas Facility. The samples are to be analyzed for asbestos fibers. These are in addition to the 136 previously sent in.

The cost of the analysis will be against the existing Purchase Order No. of 0526-133415. Please call me at (512) 831-4501 as soon as the results are available. You can fax the results to us at (512) 831-5278.

Thank you,


Belia Cortez
Site Manager



CHAIN OF CUSTODY

REPORT TO:		INVOICE TO:		☒ CHECK BOX IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME PQ. # RELEASE #
COMPANY		COMPANY		
ADDRESS		ADDRESS		
CITY		CITY		
STATE		STATE		
ZIP		ZIP		
ATT. B. CORTES		ATT.		
PHONE (512) 831-4501		PHONE #		
CLIENT COMMENTS		NUS COMMENTS & SAMPLE #S		
INSULATION SAMPLES FOR ASBESTOS ANALYSIS				

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.


NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

WARRANTY AND LIMITATION OF LIABILITY				REQUESTED ANALYSIS	
SAMPLE SOURCE & DESCRIPTION				CONTAINERS NUMBERS	REMARKS
S N A M P L E #	D A T E	T I M E	C O M P O S I T E		
1 326	11-7-90	10AM	✓	BLOG. 428 FLOOR	✓
2 327				" " CEILING	
3 328				" " "	
4 329				" 525 " PIPE	
5 330				" 525 FLOOR	
6 331				" 523 FLOOR	
7 332				" " CEILING	
8 333				" 522 FLOOR	
				" " CEILING	
				" 821 FLOOR	
				" " CEILING	
				" 489 FLOOR	
				" " CEILING	
				" 625 FLOOR	
				" 625 CEILING	
SUSHO BY SIGN <i>[Signature]</i> DATE/TIME 5PM 11/7/90				RELINQUISHED BY SIGN	DATE/TIME RECEIVED BY SIGN
SUSHO BY SIGN				DATE/TIME	RECEIVED FOR LABORATORY BY SIGN
DATE/TIME				SAMPLE CONDITION	CARRIER PHONE #
DATE/TIME					DATE RESULTS REPORTED BY SIGN
DATE/TIME					DATE/TIME



CHAIN OF CUSTODY

REPORT TO:		INVOICE TO:		☒ CHECK BOX IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME	
COMPANY		COMPANY			
ADDRESS		ADDRESS			
CITY		CITY		STATE ZIP	
ATT		ATT		PHONE #	
CLIENT COMMENTS		NUS COMMENTS & SAMPLE #S		RELEASE #	
PROJECT NAME/SITE NAME					
INSULATION SAMPLES FOR ASBESTOS ANALYSIS					
WARRANTY AND LIMITATION OF LIABILITY					
Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict. NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.					
CONTAINER NUMBER		SAMPLE SOURCE & DESCRIPTION		REQUESTED ANALYSIS	
1 311		✓ BLDG. 123 FLOOR		ASBESTOS	
2 312		" " PIPE			
3 313		" 230 CEILING			
4 314		" 224 "			
5 315		" " A/C DUCT			
6 316		" 230 FLOOR			
7 317		" 420 "			
		" " CEILING			
		" 422 "			
		" 424 PIPE			
		" 425 FLOOR			
		" 424 CEILING			
		" 424 PIPE			
		" 425 "			
		" " A/C DUCT			
DATE TIME		DATE TIME		DATE TIME	
11-7-90 10AM		5:24 PM 11/7/90			
SIGNED BY		RECEIVED BY SIGN		RECEIVED BY SIGN	
SIGNED BY		RECEIVED FOR LABORATORY BY SIGN		RECEIVED FOR LABORATORY BY SIGN	
AIR BILL NO		AIR BILL NO		DATE RESULTS REPORTED BY SIGN	
DATE TIME		DATE TIME		DATE TIME	



NUS CORPORATION HOUSTON ANALYTICAL LABORATORY 1800 GEMVA AVENUE, CLEAR LAKE CITY HOUSTON, TEXAS 77008-2783 713-488-1810	PROJECT NAME/SITE NAME INSULATION SAMPLES FOR ASBESTOS ANALYSIS		CLIENT COMMENTS FINISHED. FAX NO. (512) 831-5278		NUS COMMENTS & SAMPLE FS		CHECK BOX ☒ IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
	REPORT TO: COMPANY UNION CARBIDE CORP. ADDRESS STAR ROUTE BOX 90 CITY BROWNVILLE TX ZIP 77521 ATT. B. CORTEZ PHONE (512) 831-4501		INVOICE TO: COMPANY ADDRESS CITY STATE ZIP PHONE #		P.Q. # RELEASE #		

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise, for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information analyzed. In no event shall NUS be liable, whether in contract or tort, or otherwise, for any action related to such use of interpretation.

SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRADES	SAMPLE SOURCE & DESCRIPTION	CONTAINER NUMBER	REQUESTED ANALYSIS	REMARKS
1	11-7-90	10AM						
2	267				BLDG. 166 ROOF TAR S. END CENTER	1		
3	268				" " " FIBER " " "			
4	269				" 167 " LAYER UNDER TAR			
5	270				" " " TAR N. END CENTER			
6	300				" 168 PIPE			
7	301				" " "			
8	302				" 161 CEILING			
9	303				" " PIPING			
10					" " FLOOR			
11					" 162 PIPE			
12					" 164 "			
13					" 167 CEILING			
14					" 166 "			
15					" 221 "			
16					" 123 "			
DISPATCHED BY SIGN					DATE/TIME	RECEIVED BY SIGN	DATE/TIME	RECEIVED BY SIGN
12-1-90					5:24 PM	11/7/90		
DISPATCHED BY SIGN					DATE/TIME	RECEIVED FOR LABORATORY BY SIGN	DATE/TIME	SAMPLE CONDITION
								CARRIER PHONE #
E R C O						AIR BILL NO		DATE RESULTS REPORTED BY SIGN
								DATE/TIME



CHAIN OF CUSTODY

REPORT TO:		INVOICE TO:		☒ CHECK BOX IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
COMPANY UNION CARBIDE CORP.		COMPANY		
ADDRESS STAR ROUTE BOX 90		ADDRESS		
CITY BROWNVILLE TX 77821		CITY STATE ZIP		
ATTN B. CORTEZ		PHONE (512) 831-4501		RELEASE
PROJECT NAME/SITE NAME		NUS COMMENTS & SAMPLE #S		

INSULATION SAMPLES
FOR ASBESTOS
ANALYSIS

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict. NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

S A M P L E #	DATE	TIME	COM P O S I T E	G R A B	SAMPLE SOURCE & DESCRIPTION	CONTAINERS NUMBER	REQUESTED ANALYSIS		REMARKS
1	11-7-90	10AM			BLDG. 625 A/C DUCT	1			
2	11-7-90				" 731 FLOOR				
3	11-7-90				" " CEILING				
4	11-7-90				" " A/C DUCT				
5	11-7-90				" " PIPE				
6	11-7-90				" 168 ROOF CENTER				
7	11-7-90				" " ROOF B TAR				
8	11-7-90				" " TOP LAYER				
9	11-7-90				" 259 CEILING HALL				
10	11-7-90				" 259 R. Room PIPE				
11	11-7-90				" 731 ROOF (TOP)				
12	11-7-90				" 422 PIPE IN CEILING				
13	11-7-90				" " "				
14	11-7-90				" 731 ROOF (Bottom)				
15	11-7-90				" " MIDDLE LAYER				
RELINQUISHED BY SIGN: <i>Blax (Cortez)</i> DATE/TIME: 5:24 PM 11/9/90									
RECEIVED FOR LABORATORY BY SIGN: DATE/TIME: RECEIVED BY SIGN: DATE/TIME:									
AIR BILL NO: CARRIER PHONE # DATE RESULTS REPORTED BY SIGN DATE/TIME:									

UNION CARBIDE CORPORATION
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78520
(512) 831-4501

BULK SAMPLES:

SAMPLE NO.	DESCRIPTION
267	BLDG. 166 ROOF TAR S END CENTER
268	BLDG. 166 ROOF FIBER S END CENTER
269	BLDG. 167 ROOF LAYER UNDER TAR
270	BLDG. 167 ROOF TAR N END CENTER
300	BLDG. 168 PIPE
301	BLDG. 168 PIPE
302	BLDG. 161 CEILING
303	BLDG. 161 PIPING
304	BLDG. 161 FLOOR
305	BLDG. 162 PIPE
306	BLDG. 164 PIPE
307	BLDG. 167 CEILING
308	BLDG. 166 CEILING
309	BLDG. 221 CEILING
310	BLDG. 123 CEILING
311	BLDG. 123 FLOOR
312	BLDG. 123 PIPE
313	BLDG. 230 CEILING
314	BLDG. 224 CEILING
315	BLDG. 224 A/C DUCT
316	BLDG. 230 FLOOR

SAMPLE NO.	DESCRIPTION
317	BLDG. 420 FLOOR
318	BLDG. 420 CEILING
319	BLDG. 422 CEILING
320	BLDG. 424 PIPE
321	BLDG. 425 FLOOR
322	BLDG. 424 CEILING
323	BLDG. 424A PIPE
324	BLDG. 425 PIPE
325	BLDG. 425 A/C DUCT
326	BLDG. 428 FLOOR
327	BLDG. 428 CEILING
328	BLDG. 428 CEILING
329	BLDG. 525 CEILING
330	BLDG. 525 PIPE
331	BLDG. 523 FLOOR
332	BLDG. 523 CEILING
333	BLDG. 522 FLOOR
334	BLDG. 522 CEILING
335	BLDG. 821 FLOOR
336	BLDG. 821 CEILING
337	BLDG. 489 FLOOR
338	BLDG. 489 CEILING
339	BLDG. 625 FLOOR
340	BLDG. 625 CEILING

BULK SAMPLES - UNION CARBIDE BROWNSVILLE, TEXAS PAGE 3

SAMPLE NO.	DESCRIPTION
341	BLDG. 625 A/C DUCT
341A	BLDG. 731 FLOOR
342	BLDG. 731 CEILING
343	BLDG. 731 A/C DUCT
344	BLDG. 731 PIPE
345	BLDG. 168 ROOF CENTER
346	BLDG. 168 ROOF B TAR
347	BLDG. 168 ROOF TOP LAYER
348	BLDG. 259 CEILING HALL
349	BLDG. 259 R. ROOM PIPE
371	BLDG. 731 ROOF (TOP)
372	BLDG. 422 PIPE IN CEILING
373	BLDG. 422 PIPE IN CEILING
374	BLDG. 731 ROOF (BOTTOM)
375	BLDG. 731 ROOF MIDDLE LAYER