

**Region 6 - Enforcement & Compliance Assurance Division**  
**INSPECTION REPORT**

|                                        |                                                                         |                  |
|----------------------------------------|-------------------------------------------------------------------------|------------------|
| Inspection Date(s):                    | 2/25/2020                                                               |                  |
| Media Program:                         | Water, Clean Water Act, National Pollution Discharge Elimination System |                  |
| Regulatory Program(s)                  | Oil and Gas, Produced Water                                             |                  |
| Company Name:                          | <b>JnK Energy Corporation</b>                                           |                  |
| Facility Name:                         | <b>Grace Jennings Estate</b>                                            |                  |
| Facility Physical Location:            | 34.0052176N, -98.9045987W                                               |                  |
| (city, state, zip code)                | Electra, Texas, 76360                                                   |                  |
| Mailing address:                       | 1705 Quail Valley Rd.                                                   |                  |
| (city, state, zip code)                | Iowa Park, TX 76367                                                     |                  |
| County/Parish:                         | Wichita County                                                          |                  |
| Facility Phone Number                  | (940) 583-4141                                                          |                  |
| Facility Contact:                      | Patric Kennedy                                                          | Registered Agent |
|                                        | N/A                                                                     |                  |
| FRS Number:                            | N/A                                                                     |                  |
| Identification/Permit Number:          | TXU011249                                                               |                  |
| Media Identifier Number:               | N/A                                                                     |                  |
| NAICS:                                 | 211111                                                                  |                  |
| SIC:                                   | 1311                                                                    |                  |
| Personnel participating in inspection: |                                                                         |                  |
| Kayla Woods                            | U.S. EPA, Region 6, ECDWE                                               | Inspector        |
| Jeanne Eckhart                         | U.S. EPA, Region 6, ECDWE                                               | Inspector        |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
|                                        |                                                                         |                  |
| EPA Lead Inspector<br>Signature/Date   |                                                                         | 25 MAR 2020      |
|                                        | Kayla Woods                                                             | Date             |
| Supervisor<br>Signature/Date           |                                                                         | 30 MAR 2020      |
|                                        | Guy Tidmore                                                             | Date             |

## **Section I – INTRODUCTION**

### **PURPOSE OF THE INSPECTION**

EPA Region 6 inspectors Kayla Woods and Jeanne Eckhart arrived at the JnK Energy Corporation/Grace Jennings Estate Lease at 10:33AM on 2/25/2020 for an unannounced inspection. The scope of the inspection was to determine if the facility is in compliance with the Clean Water Act (CWA), and to identify and document unauthorized discharges of produced wastewater (brine) to a water of the United States.

### **FACILITY DESCRIPTION**

There was a sign indicating that this facility is currently owned by JnK Energy Corporation and is the Grace Jennings Estate Lease. I observed two storage tanks and a separator at the facility.

## **Section II – OBSERVATIONS**

I observed that there was inadequate secondary containment walls (berms) around the storage tank area. The berms were very low and inadequate due to erosion. I observed vegetation within a foot or two feet of the tanks inside the secondary containment area. I observed no spills and no staining at the facility.

## **Section III – AREAS OF CONCERN**

There was inadequate secondary containment berms and vegetation within the secondary containment area.

## **Section IV – FOLLOW UP**

EPA Region 6 Water Enforcement will refer this facility to EPA Region 6 SPCC program.

## **Section V – LIST OF APPENDICES**

There are no photos, videos, or other appendices to include to this report.