

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	2/25/2020	
Media Program:	Water	
Regulatory Program(s)	CWA - Brine	
Company Name:	Slant Operating, LLC	
Facility Name:	Denney Lease	
Facility Physical Location:	34.0383548, -99.2830654	
(city, state, zip code)	Vernon, Texas 76384	
Mailing address:	206 E. 9 th St., Ste. 1300	
(city, state, zip code)	Austin, Texas 78701	
County/Parish:	Wichita County	
Facility Phone Number	940-264-4455	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011251	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Jeanne Eckhart	EPA 6 ECDWE	Inspector
Kayla Woods	EPA 6 ECDWE	Inspector
EPA Lead Inspector Signature/Date		
	Jeanne Eckhart	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Jeanne Eckhart and Kayla Woods visited the Slant Operating, LLC oil and gas facility located near Vernon, Texas on 02/25/2020 for an unannounced inspection. There were no representatives of Slant Operating, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility was located on the Denney Lease and was an active tank battery with 2 storage tanks and a separator on site.

Section II - OBSERVATIONS

I observed that the tank battery did not have secondary containment. I observed significant damage outside of the containment area near the creek that runs by the facility at the time of the inspection. I saw vegetation in the contaminant area of the tank battery as well.

Section III – AREAS OF CONCERN

There was vegetation in the tank battery area and no secondary containment.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A