

PLAINTIFF'S EXHIBIT

SH-589

7.25
adjustedDPMC-2729
(4/12/89)INSULATION INSPECTION SUMMARYFROM G.L. RuchmanDATE 10/07/91TO R. CHOUFFOTDEPT/UNIT ALKY/THRML CKGMGR ALKY/THRML CKG

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HSB-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
DUBB'S #9	H-5 (TUBE PLUG)	Amosite X	
DUBB'S #9	H-5 (ROOF)	Chrysotile X	
DUBB'S #9	H-5 (Box Door)		Fiberglass X
DUBB'S #9	H-5 (Between walls)		Fiberglass X
DUBB'S #9	H-5 (Bottom of H-5)		Fiberglass X

cc: Health & Safety Satellite
Information Copy

LAM 016947

DPMC-10689

725
Asbestos

FROM

DATE _____

1-24-91

TO

DEPT/UNIT

Unit	Equipment	Asbestos	Non-Asbestos
------	-----------	----------	--------------

North Bay of Refinery Docks
Steam Piping to Unit Heater

X

LAM 016948

DPMC-10690

DPMC-2729
(4/12/89)

FROM ST. BURNHAM HEALTH & SAFETY DATE 12-16-91
TO B&R SAFETY MATT HODGE DEPT/UNIT CR-3 DHT

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HSB-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
DHT CR-3	Pipe RACK	Chrysotile X	
OP-ITT	VOL-150		Fiber Glass

cc: Health & Safety Satellite
Information Copy

LAM 016949

DPMC-10691

DPMC-2729
(4/12/89)

INSULATION INSPECTION SUMMARY

FROM 2-17-68

DATE 12-11-91

TO 100-44747-1A-100-2

DEPT/UNIT Olefins / Pyrolysis

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HSB-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

[illegible]

cc: Health & Safety Satellite
Information Copy

LAM 016950

725

725

725

725

725

725

725

725

725

DPMC-2729
(4/12/89)


INSULATION INSPECTION SUMMARY

FROM GE. SUGHANAN Health & Safety DATE 11/07/91
TO H.L. STOKES DEPT/UNIT ATC (FLASHER)

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HSB-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
DUBBS 1-7 Row	SUB-SOIL	AMOSITE X	
(4) SAMPLES "SEE BELOW"			

#3 SAMPLE		
#2 SAMPLE		#4 SAMPLE
#1 SAMPLE		



cc: Health & Safety Satellite
Information Copy

LAM 016952

DPMC-10694

DPMC-2729
(4/12/89)

INSULATION INSPECTION SUMMARY

FROM G. L. Buchanan HEALTH & SAFETY DATE 10/11/91
TO 11/15/91 DEPT/UNIT O.P. G.I.

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HSB-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

[illegible]cc: Health & Safety Satellite
Information Copy

LAM 016953

725
ask

DPMC-2729
(4/12/89)

INSULATION INSPECTION SUMMARY

FROM GERALD BUCHANAN

DATE 10/07/91

TO R. CHOUFFOT
MGR. ALKY/THRML CKG

DEPT/UNIT ALKY/THRML CKG

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HSB-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
Dubbs #9	H-5 (TUBE - PLUG)	Amosite X	
Dubbs #9	H-5 (ROOF)	Chrysotile X	
Dubbs #9	H-5 (Box DOOR)		Fiber Glass X
Dubbs #9	H-5 (BETWEEN WALLS)		FIBER GLASS X
Dubbs #9	H-5 (BOTTOM OF H-5 WALL)		FIBER GLASS X

cc: Health & Safety Satellite
Information Copy

LAM 016954

DPMC-10697

725
Asbestos

FROM G.L. BUCHANAN HEALTH & SAFETY DATE 06/07/91
TO RUDY ZUBIA DEPT/UNIT N/MOA
WAY CONSTRUCTORS

cc: ~~Health & Safety Satellite~~
~~Information Copy~~

DPMC-10699

725
Aspen Ave

FROM A. CRADDOCK DATE 4-12-91
TO K. SODERMAN DEPT/UNIT LUBE LOGISTICS

1th & Safety Satellite
Information Copy

DPMC-10700

7-5
A.L.

INSULATION INSPECTION SUMMARY

FROM G. L. BUCHANAN HEALTH & SAFETY DATE 03/22/91
TO SIP DEPT/UNIT Aromatics Stabilizer

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HS8-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
Thermatics stabilizer	V-1008	Amosite X	

co: Health & Safety Satellite
Information Copy

LAM 016959

DPMC-10701

725
Asbestos

DPMC-2729
(4/12/89)

INSULATION INSPECTION SUMMARY

FROM Gary Buchanan

DATE 03/11/91

TO Braun & Root

DEPT/UNIT CCU / HT-2

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HS8-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
① CCU	Lines P-1546 & P-1547	AMOSITE	
② "	"	Chrysotile	
③ "	"	Chrysotile	
④ "	"	AMOSITE	
⑤ "	"	AMOSITE	
⑥ "	"	AMOSITE	
⑦ "	"	AMOSITE	
⑧ "	"	AMOSITE	
⑨ "	"	Chrysotile	
⑩ "	"	Chrysotile	
HT-2	K-OL-602 Piping	Fiber Glass	
"	"	Fiber Glass	

cc: Health & Safety Satellite
Information Copy

LAM 016960

DPMC-10702

DPMC-2729
(4/12/89)

INSULATION INSPECTION SUMMARY

FROM GL. BUCHANAN HEALTH & SAFETY DATE 03/19/97
TO STEVE SHIPPY DEPT/UNIT LD-III

The following equipment has been inspected for insulation containing asbestos. The original inspection summary has been filed in the Health and Safety Satellite, HS8-115 to be in compliance with OSHA 1910.1001 and SHELL Epidemiology Study Requirements.

Unit	Equipment	Asbestos	Non-Asbestos
FRACT Ref.	North yard at Grade	AMOSITE X	
Compression	South yard at Grade	AMOSITE X CHRYSO TILE	

cc: Health & Safety Satellite
Information Copy

LAM 016961

DPMC-10703

725
asked

FROM Wesley Neal
TO Sandy Bryant

DEPT/UNIT *NMOD*[illegible]

LAM 016962

DPMC-10704

F# Montoury (Bq. Source)
Roberts 13032 Dec 1990
725

LAM 016946