


## 090-PROPELLER SHAFT BEARING SUPPORTS

REFER TO BALKAMP RUBBER PRODUCTS CATALOG

## 090-PROPELLER SHAFT BUSHINGS



**3694732**

| Car       | Years | Models               | Location          | Part No.       | Qty. |
|-----------|-------|----------------------|-------------------|----------------|------|
| CHEVROLET | 51-54 | All Pass. & 1/2 Ton  | Front (Press Fit) | <b>3694732</b> | 1    |
|           | 1950  | 1/2 Ton (2nd Design) | Front (Press Fit) | <b>3691490</b> | 1    |
|           | 51-54 | All Pass. & 1/2 Ton  | Rear (Press Fit)  | <b>3694733</b> | 1    |

## 090-TRUNNION REPAIR KIT

QUICK INEXPENSIVE REPAIR  
OF LOWER TRUNNION ASSEMBLY!



**3-4247**

Undersize sleeve unit gives tight  
fit on badly worn trunnion pin  
threads.

| Car     | Years | Models           | Part No.      |
|---------|-------|------------------|---------------|
| RAMBLER | 62-63 | Rambler American | <b>3-4247</b> |
|         | 57-61 | All              |               |
|         |       |                  |               |