

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 11/20/2024		Time 10:00	
Operator Representative Performance Energy Resources, LLC		Report Sent Operator			
Inject Interval 1848 - 1900		USDW 310		Well Type Disposal	
Annulus Fluid Type oil		Concentric Pkr		Packer Depth 1802	
Casing 4.5		Tubing 2.375			
Operator Info Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS6338000		
			API Well No		
			Lease Name Bowman		
			Well ID 3B		
			Location SE 06 27N 11E		
Type of MIT Casing - Tubing Annulus Pressure			Test Reason Routine		
Injecting N		Injection Rate (bpd)		Tubular Lining	
MIT Due 11/15/2024		MIT Freq EVERY THREE YEARS		Ann Filled (hrs)	
				Ann Press Mont	
Time		Tubing Pressure		Annulus Pressure	
Pre-Test		0		0	
Initial	10:00	0	240		
Mid	10:15	0	235		
Final	10:30	0	230		
				Flowback	Pressure
				High	230
				Mid	100
				Low	20
				End	0
				Total Volume	4200
			ADA Pressure Test - Required Test Pressure		
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)		
Fluid Migration Test Type		Remedial Action Type			
Inspection Comments		MIT observed, pressure hold OK. Inspector observed oil in the flowback.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.845836, -96.159532		
City: Bowring	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010534

Orientation: WSW

Date of Photo: 11/20/2024

Time of Photo: 11:43AM

Latitude: 36.845836

Longitude: -96.159532

Photographer: Matthew Allen

Description: This was well OS6338000 at the time of the inspection.