

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	09/18/2024	Time	09:00
		Operator Representative	Performance Energy Resources, LLC		
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS4530000		
		API Well No			
		Lease Name	JACKSON		
		Well ID	12		
Location	SE 03 24N 11E	Status	Inactive	Well Type	Disposal
Latitude	36.582553	Longitude	-96.107735		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Performance Energy Resources		
Inspect No.		Date Last MIT	01/23/2018	Last Test Result	Fail
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 542
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Speedy Well Service run in well OS4530000 to 1500 feet below land surface where the tubing was obstructed. Plugging operation postponed until 1" steel tubing and workover rig was available to remove the tubing obstruction.				
Inspector Signature					
Supervisor Signature					