

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	05/10/2024	
Media Program:	Water (CWA)	
Regulatory Program(s)	Water (CWA) Brine Program (Oil & Gas inspection)	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	Meekins Lease Tank Battery	
Facility Physical Location:	Off Union Road 434 at 33.356248, -92.782366	
(city, state, zip code)	Smackover, AR 71762	
Mailing address:	100 East 7th Street	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry Langley jloc58@yahoo.com	Owner / Operator
FRS Number:	N/A	
Identification/Permit Number:	ARU002228	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Kerri McCabe (lead)	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Michael Blaha	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Kerri McCabe	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Kerri McCabe (lead) and Michael Blaha arrived at the Jerry Langley Oil Co., LLC / Meekins Lease Tank Battery, located off Union Road 434 at 33.356248, -92.782366; at 1224 on 05/10/2024 for an unannounced inspection. No facility representatives were present at the time of the inspection. Mr. Jerry Langley and Mr. Peanut Thompson were notified of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted a follow-up inspection on the Jerry Langley Oil Co., LLC / Meekins Lease Tank Battery, which contains an oil-water separator and three (3) storage tanks.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, oil-water separator, pipes and valves, and storage tanks located at the facility; see Appendix 1 (Photograph Log), Photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed the transfer pipe on top of the secondary containment berm with a newly installed catch bucket at the pipe, see Photo No. 3.

I observed the backside of the facility, and the secondary containment area was free of loose oil and leaks, see Photo No. 4.

I observed overhead pipes to be supported to and from the storage tanks, see Photo No. 5.

I observed the two (2) drainpipes for secondary containment to have screwcaps installed, see Photo No. 6.

I observed the front of the facility, and the secondary containment area was free of loose oil and leaks, see Photo No. 7.

Section III – AREAS OF CONCERN

No closing conference was held due to no personnel with Jerry Langley Oil Co., LLC being present during the inspection. There were no areas of concern noted during the inspection.

Section IV – FOLLOW UP

There were no areas of concern during the inspection, and a follow-up inspection is not required at this time.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 7 photos taken 05/10/2024.

Appendix 1

Photograph Log 7 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0055

Orientation: NE

Date of Photo: 05/10/2024

Time of Photo: 1234

Latitude: 33.356225

Longitude: -92.782325

Photographer: Kerri McCabe

Description: Looking NE, this photo showed the signage at the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0056

Orientation: NE

Date of Photo: 05/10/2024

Time of Photo: 1235

Latitude: 33.356075

Longitude: -92.782408

Photographer: Kerri McCabe

Description: Looking NE, this photo showed the overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0057

Orientation: E

Date of Photo: 05/10/2024

Time of Photo: 1237

Latitude: 33.356250

Longitude: -92.782386

Photographer: Kerri McCabe

Description: Looking E, this photo showed a catch bucket installed at the transfer pipe.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0058

Orientation: N

Date of Photo: 05/10/2024

Time of Photo: 1238

Latitude: 33.356139

Longitude: -92.782303

Photographer: Kerri McCabe

Description: Looking N, this photo showed an overview of the tanks from the backside of secondary containment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0059

Orientation: SW

Date of Photo: 05/10/2024

Time of Photo: 1239

Latitude: 33.356234

Longitude: -92.782265

Photographer: Kerri McCabe

Description: Looking SW, this photo showed that piping for the storage tanks had been stabilized.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0060

Orientation: W

Date of Photo: 05/10/2024

Time of Photo: 1240

Latitude: 33.356341

Longitude: -92.782197

Photographer: Kerri McCabe

Description: Looking W, this photo showed the drainpipes for secondary containment with shutoff valves and screw caps in place.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Location: Jerry Langley Oil Co, LLC – Meekins Lease Tank Battery from Mount Holly Hwy (160) off Union Co Rd 434 at 33.356248, -92.782366.

City: Smackover

County/Parish: Union

State: Arkansas



Photo File Name: IMG_0061

Orientation: S

Date of Photo: 05/10/2024

Time of Photo: 1241

Latitude: 33.356319

Longitude: -92.782293

Photographer: Kerri McCabe

Description: Looking S, this photo showed an overview of the front of the tank battery.