

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/06/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Arcadia Operating, LLC	
Facility Name:	Norman Prince Lease	
Facility Physical Location:	33.338185, -95.173045	
(city, state, zip code)	Talco, Texas 75487	
Mailing address:	3811 Turtle Creek Blvd., Ste. 1900	
(city, state, zip code)	Dallas, Texas 75219	
County/Parish:	Titus County	
Facility Phone Number	214-446-1502	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011264	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Arcadia Operating, LLC oil and gas facility located near Talco, Texas on 03/06/2020 for an unannounced inspection. There were no representatives of Arcadia Operating, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the Norman Prince Lease and has state identification number of: RRC No. 01737. This lease was a sour gas production lease.

Section II - OBSERVATIONS

I observed that the brine pump leaked into a small sump in the secondary containment area. There was a larger separate pit with 1-2 feet of fluids in it at the facility. I observed a drainpipe and valve in the secondary containment that was next to a marsh.

Section III – AREAS OF CONCERN

There were fluids in the secondary containment area.

Section IV – FOLLOW UP

EPA water enforcement will refer this to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A