

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	1/7/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Perdure Petroleum, LLC	
Facility Name:	Carrie-Monroe	
Facility Physical Location:	36.842367, -96.757751 (SW Sect. 3, T 27N, R 5E)	
(city, state, zip code)	Shidler, Oklahoma 74652	
Mailing address:	1833 S. Morgan Rd.	
(city, state, zip code)	Oklahoma City, Oklahoma 73128	
County/Parish:	Kay County	
Facility Phone Number	918-793-2881	
Facility Contact:	Carl Thumen	
	cthunem@perdurepetro.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		28 FEB 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Perdure Petroleum, LLC oil and gas facility located at latitude 36.842367 and longitude -96.757751 near Shidler, Oklahoma on 01/07/2020 for an unannounced inspection. There were no representatives of Perdure Petroleum, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Carrie-Monroe tank battery.

Section II - OBSERVATIONS

I observed a dry secondary containment at the tank battery. There was a sump pump installed. I observed historical surface damage west and south of the tank battery indicative of a produced water release.

Section III – AREAS OF CONCERN

Some surface damage was observed outside of the secondary containment area of the tank battery.

Section IV – FOLLOW UP

N/A

Section V – LIST OF APPENDICES

N/A