



Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

This report includes only factual information gained by documentation, onsite observations, and/or onsite interviews.

Inspector Name(s)	Chelsey Sherwood and Tom Nystrom	Time In	2:50 PM	Start Date	March 28, 2024
		Time Out	3:15 PM	End Date	March 28, 2024
Inspector's Organization	EPA Region 6, Enforcement and Compliance Division, Water Resources Section				
Organization Requesting Inspection (if different)	N/A				
Inspection Type	Evaluation	Inspection Status	Original		
Site Name	ARDOT, Caddo River				
Site Address*	HWY 70				
City*	Glenwood	County*	Montgomery	State*	AR Zip Code* 71943
Mailing Address*	10324 Interstate 30				
City*	Little Rock	County*	Pulaski	State*	AR Zip Code* 72209
Latitude*	34.32162	Longitude*	-93.55248		
Estimated Size of Site (acres)	3	Is there a home on the site?	☐ Yes ☒ No		
Inspector Signature	CHELSEY SHERWOOD Digitally signed by CHELSEY SHERWOOD Date: 2024.05.16 12:04:56 -05'00'			Date	5/15/2024
Supervisor Signature	SAMANTHA DOUPNIK Digitally signed by SAMANTHA DOUPNIK Date: 2024.05.16 12:16:07 -05'00'			Date	5/16/2024

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	ARDOT, Caddo River	Start Date	March 28, 2024
		End Date	March 28, 2024
Inspection Purpose	Initial site visit		
Opening Conference			
☐ Presentation of Inspector Credentials			
Name and Title (Use N/A if owner/operator not available to join the inspection)			
N/A			
☐ Opening Conference			
Name of person authorizing access if applicable			
N/A			
Notes from Opening Conference			
N/A			
☐ Access Issues if Any			
Describe			
N/A			
Inspection Observations and Sample Collection			
Site Owner/Site Operator/Responsible Party (Name, title and contact information)			
ARDOT Phone number is 501-569-20000			
Additional Persons Present at Inspection			
N/A			
General Site Characteristics (layout of property, etc.)			
The property is along the HWY 70 bridge that crosses the Caddo River in Glenwood, AR. Refer to map attachments for details.			
Purpose and Need for Discharge of Dredged and/or Fill Material			
Bridge Maintenance			
Site Overview (Past inspections, site description, permits, etc.)			
None known.			
Scope of Inspection (Areas inspected or not inspected)			
The areas inspected was the work being done along the Caddo River north and south of the HWY 70 bridge.			

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	ARDOT, Caddo River	Start Date	March 28, 2024
		End Date	March 28, 2024
Environmental Conditions (e.g., wind, rain, smoke, dust, temperature, snow)			
~67 degrees F, sunny			
Field Work Conducted			
We assessed the work being conducted along HWY 70 in the Caddo River. Pictures were taken for documentation.			
Closing Conference			
Documents Received and/or Requested During the Inspection			
N/A			
Compliance Assistance Provided (If any)			
N/A			
Observations Relayed to Site Owner/Operator			
N/A			
Actions Taken by Owner/Operator During the Inspection (If any)			
N/A			
Potential Issues of Concern Including Regulatory Citations			
This was a Section 404 compliance inspection to assess potential impacts to Waters of the United States. This report will be sent to the Vicksburg District Corps District for evaluation. Refer to photos and map attachments.			
Attachments*			
☒ Maps and Sketches			
☒ Photographs (including location) and Photo Log			
☐ Other (SSIP, Wetlands Delineation Forms, etc.)			
N/A			
Additional Notes			
N/A			

Appendix 1

Photograph Log



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 1

Location: 34.32209, -93.55235		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
1.jpg	03/28/2024, 3:02 PM	Chelsey Sherwood	Showing construction work being done on river right along the bridge in the Caddo River. Picture taken facing downstream, southwest.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 34.32209, -93.55235		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
2.jpg	03/28/2024, 3:02 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river left in the Caddo River. Picture taken facing downstream, southeast



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 34.32181, -93.55235		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
3.jpg	03/28/2024, 3:02 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river left in the Caddo River. Picture taken facing downstream, southeast



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 4

Location: 34.32181, -93.55235		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
4.jpg	03/28/2024, 3:03 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river right in the Caddo River. Picture taken facing west.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 34.32160, -93.55238		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
5.jpg	03/28/2024, 3:03 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river right in the Caddo River that appears to be impeding flow. Picture taken facing west.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Location: 34.32147, -93.55238		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
6.jpg	03/28/2024, 3:03 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river right in the Caddo River that appears to be impeding flow. Picture taken facing west.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Photograph Log

Photo No. 7

Location: 34.32147, -93.55238		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
7.jpg	03/28/2024, 3:03 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river right in the Caddo River that appears to be impeding flow. Picture taken facing west.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 8

Location: 34.32147, -93.55238		
City: Glenwood	County/Parish: Montgomery	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
8.jpg	03/28/2024, 3:03 PM	Chelsey Sherwood	Showing fill material below Ordinary High Water Mark along river right in the Caddo River that appears to be impeding flow. Picture taken facing downstream, south.

ARDOT, Caddo River Photo Locations



5/15/2024, 3:15:34 PM

1:2,257

0 0.02 0.04 0.07 0.09 mi
0 0.04 0.07 0.14 km

© 2024 Microsoft Corporation © 2024 Maxar ©CNES
(2024) Distribution Airbus DS © 2024 TomTom

To be used internally by EPA employees only. EPA Disclaimers: <https://www.epa.gov/web-policies-and-procedures/epa-disclaimers>
ArcGIS Web AppBuilder