

Region 6 Enforcement and Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	10/07/2019		
Media:	Water		
Regulatory Program(s)	Brine - CWA		
Company Name:	Welch Energy, LLC		
Facility Name:	Oilton Lease		
Facility Physical Location:	36.073402, -96.595248 (NW Sect. 5, T 19N, R 7E)		
(city, state, zip code)	Oilton, Oklahoma		
Mailing address:	P.O. Box 346		
(city, state, zip code)	Drumright, Oklahoma 74030		
County/Parish:	Creek County		
Facility Contact:	Leroy Welch		
	918-358-3805		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Personnel participating in inspection:			
Kent W. Sanborn	6ECDWE	Environmental Engineer	(918) 557 – 1615
EPA Lead Inspector Signature/Date			
	Kent W. Sanborn		Date
Supervisor Signature/Date			19 NOV 2019
	Guy Tidmore		Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Welch Energy, LLC oil and gas facility located at latitude 36.073402 and longitude -96.595248 near Oilton, Oklahoma on 10/07/2019 for an unannounced inspection. There were no representatives of Welch Energy, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This lease is located west of Oilton, Oklahoma.

Section II - OBSERVATIONS

The secondary containment pit was mostly dry during the inspection. There was no identification sign at the battery. I observed slight surface damage on the southwest corner of the battery.

Section III – AREAS OF CONCERN

There was no identification sign at the lease.

Section IV – FOLLOW UP

N/A

Section V – LIST OF APPENDICES

N/A