

Material: Inner lining of rubber air hose.

Source: Hose used in tank cleaning by Tank Cleaners Inc., Jacksonville, Fla.

Submitted: 7-8-48 by F.T. Mercer

Required: Lead determination at break and for sections up stream and down stream from break.

Analysis Number	Description	Size of Sample	Mg. Pb	Mg./ft. length	Mg.Pb/100 g.
48A-5819	At break	2 1/2 in. of lining	0.95	4.57	14.6
48A-5820	Section 3 ft. from break, toward short end, carrying threaded nipple	1 3/4 in. of lining	1.00	6.85	16.1
48A-5821	Section 3 ft. from break in opposite direction of #48A-5820	2 3/4 in. of lining	0.69	3.00	9.05

Reported: 7-22-48

RE 0006710

N 7654