

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/27/2024	Time	12:30
Inspection Due	2019-06-12T00:00:00Z	Operator Representative	Smith Petroleum, LLC		
Operator Info	Smith Petroleum, LLC 507 W. Main St; P.O. Box 134 Barnsdall, OK 74002-0134 Phone: 918-638-1301	Inventory ID	OS1290000		
		API Well No			
		Lease Name	Quapaw		
		Well ID	L1W		
Location	SW 20 25N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.622229	Longitude	-96.150934		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Smith Petroleum, LLC		
Inspect No.		Date Last MIT	02/04/2011	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubing s		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 120
FLM Canister Pressure		Actual Pressure	0	0	Max Volume
Lease Status	Active	Determined?	Open Hole	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Well OS1290000 (Quapaw L1W) was disconnected and not injecting at the time of the inspection. The fluid level was observed to be 879 feet below the top of the tubing. The fluid level was observed through use of the EPA Echometer. The well annulus was inaccessible and the tubing was open to the atmosphere at the time of the inspection. At the time of the inspection, the well was overdue for MIT.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.622229, -96.150934		
City: Okesa	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0073

Orientation: SE

Date of Photo: 02/27/2024

Time of Photo: 12:36 PM

Latitude: 36.22229

Longitude: -96.150934

Photographer: Matthew Allen

Description: This was well OS129000 and the well sign at the time of the inspection.